

Name of place - Construction of road & CD work Pandaul
Races to Remjanki Mandis-Valligali in
middle of Muskhari Maltakhol
Schedule XLV-Form No. 134

Date of start - 10-7-2018 Head - NABARD A.D. 02-01-2019

R.W.D. Nichalubeni DIVISION

R.W.D. Pandaul SUB-DIVISION

प्रास

M.B.N

Measurement Book

-10-1921

1921

Sri Nirmal Kumar Prasad

Sch. XLV—Form No. 134

Sch. XLV—Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
5th year Maintenance Bill					
Name of work :- 1st Maintenance					
of Road from Pandaul Bazar					
to Ram Janaki Mandir wali					
gali in middle of Mushkari					
Makhat Taluk under NABARD					
Agency :- Sri Nirmalkumar					
Prasad vill. - Sakari					
Purani Bazar, P.O. + P.S. -					
Sakari Dist - Madhubani					
Agr. No. :- 21/SBD/2018-19					
Agr. Rate :- 10.00 % below					

D.O.S. - 10.07.2018.

D.O.C. - 09.01.2019.

A.D.O.C. - 02.01.2019

Measurement

1. Restoration of rain cuts,

Berms with soil

$$5 \times 1.20 \times 0.60 \times 0.30 = 1.08 \text{ m}^3$$

$$11 \times 1.60 \times 0.90 \times 0.30 = 4.75 \text{ m}^3$$

$$20 \times 3.00 \times 1.00 \times 0.30 = 18.00 \text{ m}^3$$

$$17 \times 2.00 \times 1.00 \times 0.30 = 10.20 \text{ m}^3$$

$$21 \times 2.60 \times 1.05 \times 0.30 = 17.20 \text{ m}^3$$

$$29 \times 4.00 \times 0.85 \times 0.30 = 29.40 \text{ m}^3$$

$$71.63 \text{ m}^3$$

2. Making up of Berms/shoulder,

stripping excess soil from
Shoulders

P.T.O.

Sch. XLV—Form No. 134

Sch. XLV—Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
Material statement-					
1. Soil	—	—	—	—	100.99 m ³
2. Stone Aggregate	—	—	—	—	3.74 m ³
3. Emulsion SS-1	—	—	—	—	25.25 kg
4. Emulsion RS-1	—	—	—	—	15.29 kg
5. Bitumen S-90	—	—	—	—	215.22 kg
by					
5/1/24					
J.E.					

Abstract of cost.					
1/1 Restoration of rain					
cuts, Berms with soil.					
Qty. vol. TMB PMU					
$= 71.63 m^3$					
$@ 359.74/m^3 = 25,768/-$					
2/2 Making up of Berms/					
shoulders					
Qty. vol. TMB PMU					
$= 310.44 m^3$					
$@ 53.91/m^3 = 16,736/-$					
3/3 Repairing of pot holes.					
Qty. vol. TMB PMU					
$2.104 m^3 @ 10686.70/m^3 = 22485/-$					
Continuation					
$@ 64,989/-$					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
B/F					1364,989 =
4/4 Patch repair over					
pot holes filled.					
Qty. vol. TMB PM 43					
= 28.05 m ²					
EM 275 = 64/m ²					137732 =
5/8 Maintenance of C.D. work					
Qty. vol. TMB PM 43					
1 m. EM 287 = 7/each					2288 =
6/9 Maintenance of the					
road sign					
Qty. vol. TMB PM 43					
= 0.13 km					
EM 1067 = 411/km					139 =
7/10 Maintenance of 250 m					
1/2 K.M. stone					
Qty. vol. TMB PM 43					
= 0.29 km					
EM 647 = 56/km					132 =
8/11 (i) cutting of branches					
of trees & shrubs					
Qty. vol. TMB PM 43					
1 m. EM 104 = 48 each					1104 =
(ii) cutting of shrubs from					
road way					
Qty. vol. TMB PM 43					
4 m. EM 6 = 42 each					26 =
C/O - B 67, 678 =					

Continuation

Continuation