

कार्यपालक अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य प्रमंडल बेलसंड।

पत्रांक:- 1687 (प्रक) बेलसंड दिनांक:- 27.12.24 /

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बेलसंड

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी -सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।
ग्रामीण कार्य विभाग,
बिहार, पटना।


विषय:- MR-3054-BIHAR RURAL ROAD NEW MAINTENANCE POLICY-2018 योजना
अंतर्गत निर्माण कार्य की राशि के अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि MR-3054-BIHAR RURAL ROAD NEW MAINTENANCE POLICY-2018 योजना अंतर्गत संलग्न सुची के आधार पर पथ में निर्माण कार्य की राशि का आवंटन उपलब्ध कराने की कृपा की जाए।

अनु०- यथोक्त।

विश्वासभाजन

 27.12.24
कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेलसंड
26/12/24

Requisition for Scheme Head-MR(3054) under Bihar Rural Road Maintenance Policy-2018.

Name of Division- RWD (W) Division Belсанд

| Sl No. | Package No. | Name of Road | Project ID as per MIS | Administrative Approval (AA) Letter No & Date. | Administrative Approval (AA) | | | Agreement Amount (in Lakh) | 5 years Routine Maintenance (in Lakh) | Agreement No & Date | Date of Completion as per Agreement | Value of IRI (in mm/km) | Thickness of Bitumen Layer (in mm) | Value of Bitumen Content in Percentage | Previous Total Allocated Amount (in Lakh) | Up-to date expenditure as per MIS (in Lakh) | Requisition against work done (in Lakh) | Remarks |
|--------|-----------------------|-----------------------------------|-----------------------|--|------------------------------|---------------------|------------------------------|----------------------------|---------------------------------------|-------------------------------|-------------------------------------|-------------------------|------------------------------------|--|---|---|---|---------|
| | | | | | Length (in Km) | Amount of (in Lakh) | 5 Year Maintenance (in Lakh) | | | | | | | | | | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 |
| 1 | RM/SI/BEI/2 4/0006 | DASAIN - STARAMPUR | 31608102051 | 6120/04.12.2023 | 2.6 | 94.48 | 26.98 | 95.76214 | 26.64015 | 06 MBD/2024- 25 & 16.05.24 | 15.05.25 | 3470.1 | 25 | 5% | 0.00 | 0.00 | 95.76000 | |
| 2 | RM/SI/BEI/2 4/0006 | Madhopur Sultan Se Thahar Path | N316080002040 | 6120/04.12.2023 | 1.55 | 55.95 | 15.8 | 54.40632 | 15.17185 | 06 MBD/2024- 25 & 16.05.24 | 15.05.25 | 3256.1 | 25 | 5% | 0.00 | 0.00 | 54.40000 | |

Divisional Accounts Officer,

R.W.D. (W) Division,

Belsand

Executive Engineer,

R.W.D. (W) Division,

Belsand

22/05/24

FORM GFR 19-A

(See Government of India's Decision (10 below Rule-150)

Form of Utilisation Certificate up to the Month of Dec- 2024

PIU-Belsand

| Sl.No. | Name of Schemes | Sanction No.& Date with Amount (in Lacs Rs.) | Amount Received (in Lacs Rs.) | Particulars |
|--------|---|--|-------------------------------|--|
| 1 | Construction or Rural Roads under MR-3054 New Maintenance Policy. | MR-3054-New Maintenance Policy-2018 | | Certified that out of Rs 5887.40283 Lacs of grants-in-aid Sanctioned during the year in favour of Executive Engineer R.W.D Works Div. Belsand a Sum of Rs 5887.40283 lacs has been utilised for the purpose of New Maint. Policy-2018 Schemes as given in the margin for which it was Sanctioned and that the balance of Rs.0 lacs remaining utilized at the end of the period under report. |
| | | BRRDA | 5887.40283 | |
| | | Expenditure | 5887.40283 | |
| | | Balance Total | 0.00000 | |

Certified that I have satisfied myself that the conditions on which the grant-in aid was sanctioned have been fully fulfilled, are being fulfilled and that I have exercised the following check to see that the money was actually utilized for the purpose for which it was sanctioned .


Kind of check exercised


1. Work have been supervised by Executive Engineer/ Superintending Engineer
2. Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
3. Construction Material have been tested.
4. Measurement have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer
5. Other codal formalities have been observed.

Physical progress achieved

1. Construction of Road works.
2. Construction of CDs works .


Divisional Accounts Officer
Rural Works Department
Works Division Belsand


Executive Engineer
Rural Works Department
Works Division Belsand


26/12/24

OFFICE OF THE EXECUTIVE ENGINEER
RWD WORKS DIVISION – BELSAND


Name of Scheme – MADHOPUR SULTAN SE THAHAR PATH


PROJECT ID – N316080002040


**Certified that all item wise 100 %
Measurement has been taken by
Me**

**Certified that all item wise 50 %
Measurement has been taken by
me**

**Certified that all item wise 10 %
Measurement has been taken by
me**


**Junior Engineer
RWD Works section Runnisaipur**


**Assistant Engineer
RWD Works Sub- Division Runnisaipur**


**Executive Engineer
Rural Works Department
Works Division Belsand**

Road Name-Madhapur Sultan Se Thahar Path
Contractor Name-Vijay Kumar Roushan
Length-1.550 KM

| Date | Time | Section No. | Length In km | Bumps In mm | Speed Rate | OR mm/km | UIV | CATEGORY ROAD | IRI | Latitude | Longitude | Event |
|----------|---------|-------------|--------------|-------------|------------|----------|----------|---------------|------|-----------|-----------|--------|
| 18/12/24 | 8:48:36 | 42 | 0.1 | 250 | 10.1 | 2500 | 2972 G | | 3.99 | 26.377339 | 85.539739 | Normal |
| 18/12/24 | 8:49:4 | 42 | 0.1 | 280 | 10.1 | 2800 | 3313 G | | 4.4 | 26.377297 | 85.539730 | Normal |
| 18/12/24 | 8:49:37 | 42 | 0.1 | 260 | 10.1 | 2600 | 3086 G | | 4.13 | 26.377202 | 85.539704 | Normal |
| 18/12/24 | 8:49:57 | 42 | 0.1 | 280 | 10.1 | 2800 | 3313 G | | 4.4 | 26.375507 | 85.539173 | Normal |
| 18/12/24 | 8:50:32 | 42 | 0.1 | 290 | 20.2 | 2900 | 3426 G | | 4.53 | 26.377107 | 85.539678 | Normal |
| 18/12/24 | 8:51:37 | 42 | 0.1 | 270 | 20.2 | 2700 | 3199 G | | 4.26 | 26.377109 | 85.539675 | Normal |
| 18/12/24 | 8:52:5 | 42 | 0.1 | 280 | 10.1 | 2800 | 3313 G | | 4.53 | 26.375482 | 85.539162 | Normal |
| 18/12/24 | 8:52:38 | 42 | 0.1 | 260 | 10.1 | 2600 | 3086 G | | 4.4 | 26.374304 | 85.538992 | Normal |
| 18/12/24 | 8:53:35 | 42 | 0.1 | 290 | 20.2 | 2900 | 3426 G | | 4.13 | 26.374292 | 85.538953 | Normal |
| 18/12/24 | 8:54:6 | 42 | 0.1 | 300 | 30.3 | 3000 | 3540 G | | 4.53 | 26.374091 | 85.539156 | Normal |
| 18/12/24 | 8:54:44 | 42 | 0.1 | 280 | 10.1 | 2800 | 3313 G | | 4.66 | 26.372933 | 85.538143 | Normal |
| 18/12/24 | 8:55:19 | 42 | 0.1 | 270 | 10.1 | 2700 | 3199 G | | 4.4 | 26.372532 | 85.538272 | Normal |
| 18/12/24 | 8:55:54 | 42 | 0.1 | 260 | 20.2 | 2600 | 3086 G | | 4.26 | 26.373032 | 85.540482 | Normal |
| 18/12/24 | 8:56:32 | 42 | 0.1 | 280 | 30.3 | 2800 | 3313 G | | 4.13 | 26.372840 | 85.541322 | Normal |
| 18/12/24 | 8:57:2 | 42 | 0.1 | 260 | 10.1 | 2600 | 3086 G | | 4.4 | 26.372779 | 85.544932 | Normal |
| | | | | | | | | | 4.13 | 26.372823 | 85.544860 | Normal |
| | | | | | | | IRI | 52097 | | | | |
| | | | | | | | AVG. IRI | 3256.1 G | | | | |

$$Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$$

$$X = 2600$$

$$Y = 3086$$

(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001

L. J
18/12/24
JG


Skrumar
18.12.24.

Dr
27-12-24
EE.

Name of Customer : Vijay Kumar Roushan
Name of Work/ Road : Madhopur Sultan Se Thahar Pt
Lab Job number : 153
Date : 18-12-2024
Section No. : 42

Test Date : 18-12-2024 Road Name : Madhopur Sultan Se Thahar Pt
Machine No : 490 Road Type : (R) RURAL ROAD
Start S No : MADHOPUR Side : Interval :
Start E No : THAHAR UIV Range : 1972 To 5000 1000 mm/km
Weather : NORMAL Dist Range : 0 To 1.7 0.1 * 1000 m
Start Location : 0.00 Equation : $Y = 0 * X^2 + 1.136 * X + 132.5$
End Location : 1.550

Print Generate Report and Graph Redraw Graph Map View



L. J
18/12/24
JE

Sreemath
18.12.24
AE

LD
27-12-24