

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
Abstract of cost					
(1) Restoration of main wall with soil					
41.92 sq mds by (57)					
at 398.00/sq —				Rs	16631
$\frac{2}{2}$) Working up sections. Shoulder exposed soil					
503.24 sq mds by (57)					
at 59.88/sq —				Rs	30129
$\frac{3}{3}$) Patch repair on bituminous surface					
33.08 sq mds by (52)					
at 299.08/sq —				Rs	9894
$\frac{4}{4}$) Point of slab column					
01 sq mds by (52)					
at 2329.21/sq —				Rs	2329
$\frac{5}{5}$) Point of road sides - 20.					
0.77014 sq mds by (52)					
at 1077.81/sq —				Rs	830
$\frac{6}{16}$) Point of 200 mm 15% stone					
1.530 sq mds by (52)					
at 707.26/sq —				Rs	1082

Continuation

Continuation