

Soil = 213.136 m³

Stone metal = 5.25 m³

Stone Screening = 1.312 m³

10mm Stone chips = 2.75 m³

Stone dust = 0.056 m³

SS-1 = 59.71 kg

RS-1 = 3863 kg

VG-10 = 26695 kg

4th Year ABSTRACT OF COST

N/W - Maint. of Road from Amara

Tadlab Amari Path to Amara

Agency - Kanhaiya Mehta

Ag. No - 4/S BD/2019-20

Date of start - 30/08/2019

Actual date of comp - 28/05/2020

① Restoration of Rainwater

Beams do — do

Qty vide TMB P. NO - (74)

I. No (1) 89.0 m³ @ 370.32 = 32958.20

② Making up of Beams

Shoulder do — do

Qty vide TMB P. NO - (74)

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	D.	
I. No. (2) 494.47 m ² @			57.35	228	35820
(3) Repair of Pot hole fill					
75 mm do — do —					
Qty vide TMB P. No - (75)					
I. No. (3) 5.25 m ³ @			117.08	17	6146820
(4) Patch repair Over pot					
holes 20mm do — do —					
Qty vide TMB P. No - (75)					
I. No. (4) 70.25 m ² @			31.5	46	22161200
(5) Patch repair Over Bitumen					
20mm premix do — do —					
Qty vide TMB P. No - (75)					
I. No. (5) 70.25 m ² @			332.69		23371200
(6) Maint. of HPC — do —					
Qty vide TMB P. No - (75)					
I. No. (6/7) 7. No @			1109.67		7768200
(7) Maint. of Road signs —					
Qty vide TMB P. No - (75)					
I. No. (7/9) 0.17 km @			1066.50		176200
(8) Maint. of 200 meter					
km stone post do — do —					
Qty vide TMB P. No - (75)					
I. No. (8/10) 0.20 km @			652.87		129200
(9) Cutting of branches of					
tree shrubs do — do —					
Qty vide TMB P. No - (75)					
I. No. (9/11) 3. No @			105.39		316200

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(10) white washing on paper					
well do do					
Qty vide TMB P No - (76)					
I. No. (10/12) 147 m ² @ 16.47					242120
Total				RS 2	179 126200
Less 10% Below				RS (7)	179 12200
Net payable					2 161214200
28/05/24 <i>[Signature]</i> 26.05.2024 J.E. / <i>[Signature]</i> 26/05/24 AC					