

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Sanction No.					
					2305045208
Dt.					09.05.2023
					2nd year 60 marks
T/W - Shivdhal Ke Khet 12 to Poranamp School					
Munadari Hala Hala Ambedkar Nagar					
Agency -	Sri Ram Swarath Ray				
Agreement NO.	M/MSB/15BD-39/2019-20				
Actual date of completion	19/1/2021				
①	Restoration of Pucca mason -				
	13	6.00	0.90	0.30	= 21.06 m ³
	11	7.50	0.95	0.35	= 27.13 "
	10	6.50	1.05	0.30	= 20.48 "

	8	7.20	1.00	0.35	= 20.16 "
	9	5.50	1.10	0.30	= 16.34 "
					= 105.47 m ³
②	Maintenance of E/skeletons -				
	2	5	30.00	1.10	= 330.00 m ²
	2	4	30.00	1.05	= 252.00 "
					= 582.00 m ²
③	Maintenance of bottom mason				
	Surface mason m ² m ² -				
	8	2.00	1.50		= 24.00 m ²
	10	1.50	1.50		= 22.50 "
	13	2.50	1.05		= 34.13 "
					= 80.63 m ²
④	Maintenance of H/O skeleton = 0.4 m ²				
⑤	Maintenance of 20mm Road high = 2.26 km				
⑥	Maintenance of 20mm (cm) = 2.26 km				
	Strip				
⑦	Maintenance of plaster cement = 6 m ²				

Continuation

ABSTRACT of work

95

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Rectangular RCC slab Only note - P-94					
= 105.47 m ³ @ 380.58/m ³					40,140.5
② Maintenance of E/shoulders Only note - P-94					
= 582.00 m ² @ 58.60/m ²					34,105.2
③ Maintenance of Bituminous surface work on SS - Only note - P-94					
= 80.63 m ² @ 244.98/m ²					19,753.2
④ Maintenance of H.P. Culverts Only note - P-94					
= 4 Nos @ 1117.00/each					4,468.0
⑤ Maintenance of Sleeb type culverts Only note - P-94					
= 6 Nos @ 2309.00/each					13,854.0
⑥ Maintenance of Iron 2.00 m x 2.00 m Only note - P-94					
= 2.26 km @ 735.27/km					1,662.0

⑦ Maintenance of Road works Only note - P-94					
= 2.28 km @ 1074.51/km					2,428.0
					116,410.0
Loss of 10% of above approximate					11,641.0
					1,017,69.0

22/4/2023

MATERIAL STATEMENT

① Earth					105.47 m ³
② Stone chips					2.18 m ³
③ Bituminous Emulsion P.S.I.					22.17 kg
④ Bituminum S-90					153.20 kg

22/4/2023