

4th year winding

Roula - Bihar Rewariapur
20 road to Calcutta
highly

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Agencies - Pakkash construction					
By No. - 21 SBD/12-18					
Actual width of shoulder - 1.5-1.9,					
(1) Restoration of main cuts					
2' 8" M - 50m x 1.1m x 0.3m = 2.64 cum					
2' 25" M x 1.1m x 0.3m = 16.5 cum					
					Total = 280.22
					Unit = 222.55 cum
(2) Making of Bays at shoulder					
2 x 15 M x 50m x 1.1m = 1650 cum					
					Unit = 1508.09
(3) Repair to Poles					
10 x 10 M x 50m x 3.0m x 0.025 = 375 cum					
					Unit = 358.59
(4) Removal of Bituminous					
Bituminous - 1					
10 x 25' 559m = 358.9 cum					
(5) Removal of Bituminous surface					
Area, 8m or, 4.4 = 358.9 cum					
(6) Maintenance of C.D. 1/11 - 8 M					
(7) Maintenance of Subcut - 3 M					
(8) Maintenance of road 8m 0.61/4					
(9) Maintenance of 20' x 8m - 0.720 cum					
(10) (5) Cuts of branches of trees - 8 M					
(5) Cuts of shrubs - 39.1					
(55) Trimming of grass - 10 x 20' 6.22 cum					
(55) Trimming of grass - 21.6 cum					
(11) White Washing 10 x 16 8m = 168.4					

Continuation

11/5/23
JTB

Mandana
21/5/23
m2



