

Bihar Rural Roads Asset Management Policy

Scoring Matrix

Chief Engineer : CE-4,Purnea

Circle : Madhepura

Division : Triveniganj

Pariyahi
Pradhanmantri Sadak

Batch No : RM/SU/TRI/22/0012

Name of the Road : Se Pachim Ranipatti
Nahar Ke Daya Bank to Udakishunganj
SHW Nahar Pul Tak

SL. No.	Division	Quarter	Road	BatchNo	Inspected By	Observation Status
1	Triveniganj	5	Pariyahi Pradhanmantri Sadak Se Pachim Ranipatti Nahar Ke Daya Bank to Udakishunganj SHW Nahar Pul Tak	RM/SU/TRI/22/0012	JE0907BIDYANAND	Completed

2	Batch No.	RM/SU/TRI/22/0012
3	Total Length of Road (in km)	5.035
4	Length of Road to meet required service level (in km) [1]	5.035
5	No. of Total Quarter (i.e. 3 months as a unit) in 5 years	20
6	Ordinary Maintenance Cost as per Schedule (in Lakh)	57.88090
7	Quarterly Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Rs.) [2]	289404.50

Compliance Criteria	Standard job Description	Non - Compliance		Reduction Payment(in Rs) [6]=[3]/[1]*[2]*[4]
		Length non-compliant [3]	Weighted Value for Payment Reduction (%) [4]	
I	Paved Roads (Carriageway)	0.000	60%	0.00
II	Shoulders And Embankments	0.000	10%	0.00
III	Cross Drainage Including Culverts And Bridges	0.000	15%	0.00
IV	Signage And Road Safety	0.000	10%	0.00
V	Vegetation	0.000	5%	0.00

TOTAL PAYMENT REDUCTION FOR THE MONTH (in Rs) [5]	0.00
TO BE PAID FOR THE MONTH (in Rs) [6]	289404.50