

5th Year Maintenance

Sch-XLV-Form No.154

73

Particulars	Details of actual measurement				Counts of area
	No.	L.	B.	D.	

Name of work - Maintenance of road
from Ghoraasan Bazar to Ghoraasan
Gulariaq Ward no-2 under MMSY

Agency - Ranjeet Kumar

Agreement No- 38 SBD / 2013-14

Date of Agreement - 04/03/2014

Actual date of completion - 28/02/2016

Maintenance of work done has been
done by Agency and voucher of
work done has been produced
as below for the diff Month

① For the Month of
March 2020

Abstract of cost

Sch-XLV-Form No.154

77

Particulars	Details of actual measurement				Counts of area
	No.	L.	B.	D.	
① Restoration of Reinforcement					
	$\varnothing - VHM B P 74 (2) = 67.94 M^2$				
	$P 75 (6) = 100.95 M^2$				
	$168.89 M^2$				
	length - 163.58 M				
	$R - 293 = 01/M^2 R - 49396 = 0$				
② Maintenance of earthen					
	- shoulder				
	$\varnothing - VHM B P 73 (1) = 473.06 M^2$				
	$P 74 (9) = 462.61 M^2$				
	$935.67 M^2$				
	$R - 46 = 08/M^2 R - 43116 = 0$				
③ Maintenance of bituminous					
	- surface road				
i) Repair to Pot hole,					
	$\varnothing - VHM B P 76 (8) = 130.03 M^2$				
	$R - 350.57/M^2 R - 45585 = 0$				
ii) Repair to Pot holes with					
	75 mm D.M.				
	$\varnothing - VHM B P 76 (8) = 9.76 M^2$				
	$R - 12651.54/M^2 R - 123479 = 0$				
iii) Patch repair:-					
	$\varnothing - VHM B P 76 (8) = 130.03 M^2$				
	$R - 333 = 87/M^2 R - 43413 = 0$				
④ Maintenance of fl. & ceiling					
	$\varnothing - VHM B P 74 (3) = 11 M^2$				
	$R - 843 = 37/M^2 R - 843 = 0$				

(Continuation)

$30,5832 = 0$

Particulars	Details of actual measurement				Counts of area
	No.	L.	B.	D.	
(5) Maintenance of slab elevated					
$\theta = \text{VIMB P75}(5) = 2 \text{ N/m}$					
$\therefore f_1 = 1970.97/\text{sq ft} = 3550 = 0$					
(6) Maintenance of road signs					
$\theta = \text{VIMB P75}(3) = 1.800 \text{ Km}$					
$\therefore f_1 = 85.159/\text{Km} - f_1 = 1533 = 0$					
(7) Maintenance of roads and kmc store					
$\theta = \text{VIMB P75}(2) = 0.266 \text{ Km}$					
$\therefore f_1 = 561.50/\text{Km} - f_1 = 14920 = 0$					
(8) cutting of branches of trees					
$\theta = \text{VIMB P75}(3) = 6 \text{ N/m}$					
$\therefore f_1 = 73 = 26/\text{sq ft} = 440 = 0$					
(9) cutting of shrubs					
$\theta = \text{VIMB P75}(3) = 13.88 \text{ M}$					
$\therefore f_1 = 4.48/\text{M} - f_1 = 62 = 0$					
(10) Trimming of grass and weeds					
$\theta = \text{VIMB P75}(3) = 1530 \text{ cm}$					
$\therefore f_1 = 1.49/\text{M} - f_1 = 2280 = 0$					
(11) White washing on painted					
$\theta = \text{VIMB P75}(3) = 20.81 \text{ M}$					
$\therefore f_1 = 12.38/\text{M} - f_1 = 258 = 0$					
					$f_1 = 3, 14, 104 = 0$

(Continuation)

fifth year — $157100 \div 00$

Sch-XLV-Form No.154

79

Particulars	Details of actual measurement				Counts of area
	No.	L.	B.	D.	
	B.F.	R-3,14,10	4=0		

Less 0.05 ft. below -	15	7=0
-----------------------	----	-----

As per Agreement dated 27/2/2021 for enclosure	R-3,13,947=0	
	AS per Agg-1,57,117=0	

27/2/2021	SPY-08	780=0
	27/2/2021	900

CRP		
(S)	16.8.20	
	EE	
