

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
① Restoration of rain cut vide TMBP 19					
142.20 m ³ @ Rs 404.06					
					→ 57457.
② Making up berm/ Shoulder etc etc					
vide TMBP 19					
1002.00 m ² @ Rs 60.28					
					→ 60401.00
③ Patch repair with MSS etc etc etc					
vide TMBP 19					
110.00 m ² @ Rs 240.64					
					→ 26470.
④ Maint of H.P Culvert					
vide TMBP 20					
01 NOS @ Rs 1166.58					
					→ 1167.00
⑤ Maint of Slab culvert					
vide TMBP 20					
03 NOS @ Rs 2394.96					
					→ 7185.00
⑥ Maint of road sign					
vide TMBP 20					
0.36 Km @ Rs 1104.58					
					→ 394.00

Continuation

90 Rs 153074.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B/P	H	ISB 674. w
⑦ Mound of 20m 2km from					
vide PmbP20					
0.45km @ 583.43					
					260. w
⑧ Cutting of Branch of Tree as dead					
vide PmbP20					
0.6m @ 113.64					
					682. w
⑨ Cutting of shrubs from road way as dead					
vide PmbP20					
30m @ 6.98					
					209. w
					Rs 154228. w
Add 12% GST + 1% LC (+)					20049. w
Add S.F (+)					650. w
					174924. w
less 2.57% Belmty					4496. w
					Rs 170428 = w
Sum					
JE 31.8.23					
M. Statement					
(i) E/W - 142.20m ³					
(ii) S/chips - 2.97m ³ @ 52337					
(iii) Erosion in (SS) - 0.093m ³					

Continuation

(IV) Erosion in (PS) - 0.033m³(V) B Hyman - 0.209m³

Sum

JE 31.8.23