

PANIHARA MMSY ROAD TO BUTRUK TOLLA ROAD,

Schedule XLV-Form No.-134

(MMSY SC)

DIVISION

SUB-DIVISION

TALF

MEASUREMENT BOOK

AJAZ AHMAD

No. 713

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(4) Maint. of 11 P Cultverts					
vide it-4, P-75 =			63.7	5m ²	
	@A	258.712	/m ²	A	16493 =
(5) Maint. of 11 P Cultverts					
vide it-5, P-75 =			02	mts.	
	@A	1109.667	/m ²	A	2219 =
(6) Maint. of 5/6 Cultverts					
vide it-6, P-75 =			02	mts	
	@A	2291.438	/m ²	A	4583 =
(7) Maint. of Road Sign					
vide it-7, P-75 =			0.995	k.m.	
	@A	1055.71	/k.m.	A	1051 =
(8) Maint. of km. Shows					
vide it-8, P-75 =			0.995	k.m.	
<u>7 mts</u>	@A	675.98	/k.m.	A	673 =
(9) Cutting of Branches					
vide it-9, P-75 =			02	mts	
	@A	115.938	/m ²	A	232 =
(10) Cutting of shrubs					
vide it-10, P-75 =			07	mts	
<u>7 mts</u>	@A	6424	/m ²	A	45 =
(11) Trimming of grass/woods					

