

MMSY (SC)

Const of work from Kardauli to Mirzapur Chowk

Schedule XLV-Form No.-134

DIVISION

TALE

SUB-DIVISION

MEASUREMENT BOOK

Amish Kumar Tiwari

No. 723

4th year

68

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Adjusted at Cost.					
(1) Reg. for Rain-cuts					
vide Item 1, P-65					
= 190.76 m ³					
@ Rs 392.44/m ³ - Rs 74862 =					
(2) Maint. of Shoulders					
vide Item 2, P-66 = 1659.75 m ²					
@ Rs 53.69/m ² - Rs 56898 =					
(3) P.C. 75 mm B.M. Pot holes.					
vide Item 3, P-66					
= 13.04 m ³					
@ Rs 10670.57/m ³ - Rs 139144 =					
(4) Patch Repair of Pot holes					
vide Item 4, P-66					
= 173.91 m ²					
@ Rs 22702/m ² - Rs 39481 =					
(5) Maint. of H.P. Culverts					
vide Item 5, P-67 = 08 Nos					
@ Rs 1104.35/cu - Rs 8835 =					
(6) Maint. of Slab Culverts					
vide Item 6, P-67 = 01 No.					
@ Rs 2287.21/cu - 2287 =					
(7) Maint. of Road Signs					
vide Item 7, P-67 = 2.36 km.					
@ Rs 1036.35/km - 2441 =					
(8) Maint. of K.M. Stones					
vide Item 8, P-67 = 2.36 km.					
@ Rs 604.36/km - 1423 =					
(9) Cutting of Branches					
vide Item 9, P-67 = 01 No.					
@ Rs 114.93/cu - 460 =					

Continuation

Continuation