

4th year Maintenance Bill

71

Scr. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road - Maintenance of Kered Road					
Husena Bigha More To Husena Bigha.					
Agency - M/s Rupa Construction					
Hjr No - SBD-30/2019-20					
Actual date of completion - 11/06/2020					
<u>Steps</u>					
① Restoration of rain cuts					
-----do-----do-----E/L					
	18	0.75	1.20	0.30	4.86m ³
	16	0.90	1.20	0.30	5.184m ³
	12	1.25	1.20	0.30	5.400m ³
	8	1.60	1.20	0.30	4.608m ³
	8	2.25	1.20	0.30	6.75m ³
	8	2.72	1.20	0.30	7.884m ³
					38.47m ³
② Maintenance of Earthen Shoulder					
-----do-----do-----E/L					
	2	8	2.90	1.20	55.68m ²
	2	6	3.70	1.20	53.28m ²
	2	8	4.75	1.20	91.20m ²
	2	1	5.65	1.20	13.56m ²
					212.72m ²
③ Repair of Potholes filled with 75mm BM					
-----do-----do-----E/L					
	16	0.60	0.60	0.095	0.432m ³
					0.432m ³

Continuation

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
B.P. ---					26830.00
③ Repair of pot holes filled with BM					
-----20-----20-----6.2					
3.33943	VTMBP-31				
@Rs 10370.14/cu ³					36028.00
④ Patch repair over pot holes					
-----20-----20-----6.2					
44.51547	VTMBP-32				
@Rs 291.47/m ²					12975.00
⑤ Patch repair over B.T. Surface					
-----20-----20-----6.1					
44.51547	VTMBP-32				
@Rs 291.47/m ²					12975.00
⑥ Maintenance of H.P. Culvert					
-----20-----20-----6.1					
4.00 MB	VTMBP-32				
@Rs 1117.00/MB					4468.00
⑦ Maintenance of Road Sign					
-----20-----20-----6.2					
0.150 K.M.	VTMBP-33				
@Rs 1034.51/K.M.					157.00
⑧ Maintenance of K.M. & M. stone					
-----20-----20-----6.2					
0.180 K.M.	VTMBP-33				
@Rs 651.45/K.M.					1142.00
					1494350.00

Continuation

	Material statement
① ϵ/w	70.37843
② $s/chips$	7.67943
③ Portunit	0.44843
④ Embroid	0.11543
	596
	12.7.2024
	J.E