

MMGSY (WB)

Const. of Road From Biraj To Jariahar

Schedule XLV-Form No. 134

Rd. No. 1234567890 DIVISION

Sub-Div. 1234567890 SUB-DIVISION

MEASUREMENT BOOK

622

Copy by M/S. SHIVA ENTERPRISES

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
and 4000 m ² area,					
Area of 4000 m ²					
(1) Restoration of 4000 m ²					
width 4000 m ²					
width 75 m (1)					
169.66 m ² @ Rs. 404 = 04 m ² Rs. 68553.00					
(2) making up of 4000 m ²					
stripping of 4000 m ²					
width 75 m (2)					
934.50 m ² @ Rs. 60 = 28 m ² Rs. 56332.00					
(3) Repair of 4000 m ²					
75 mm WBM. etc. 700.					
width 76 m (3)					

10000 = 51 m² Rs. 3300.00

(4) Repair of 4000 m ²					
4000 m ²					
width 76 m (4)					
129.17 m ² @ Rs. 258 = 53 m ² Rs. 33394.00					

(5) Repair of 4000 m ²					
seal surfacing etc. 700.					
width 76 m (5)					
129.17 m ² @ Rs. 275 = 58 m ² Rs. 35597.00					

(6) Filling of 4000 m ²					
excavating 4000 m ²					
width 76 m (6)					
2500.00 m ² @ Rs. 3 = 85 m ² Rs. 10780.00					

(7) making up of 4000 m² Rs. 207956.00
 width 76 m (7)
 202 m² @ Rs. 715 = 00 m² Rs. 216645.00
 424601.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					Rs. 207956.60
					457601.60
(7) Repair of 53 pieces of damaged concrete pavement					
vide P-77 item (7)					
10.50 KM Q.B. 2581.53 KM B.					2735.60
(8) Repair of existing sections					
area of damaged concrete					
219.38 KM Q.B. 24.13 KM B.					5294.60
(9) main drainage pipe works					
vide P-77 item (9)					
7 KM Q.B. 1166.58 KM B.					8166.00
(10) main drainage works					
					Rs. 2344.96 KM B. 7185.60
(11) main of road sign					
vide P-77 item (11)					
3.04 KM Q.B. 1104.59 KM B.					3358.60
(12) main of 200 mm dia. stones					
vide P-77 item (12)					
3.04 KM Q.B. 642.23 KM B.					1952.60
(13) curing of patches of tar and slurry etc. - 500.					
vide P-77 item (13)					
18 KM Q.B. 113.64 KM B.					2046.60
					Rs. 238692.60
					455887.60

Continuation