

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, मधेपुरा

पत्रांक- 1461 अनु०

दिनांक- 12/6/24

प्रेषक,

ई० विद्यानन्द प्रसाद,
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, मधेपुरा।

सेवा में,

नोडल पदाधिकारी,
3054 एम.आर. कोषांग,
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय- MR (3054) under New Maintenance Policy- 2018 के क्रियान्वित पथों के भुगतान हेतु अधियाचना के संबंध में।

प्रसंग- भवदीय पत्रांक 113 अनु० दिनांक 10.01.2020

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के संबंध में कहना है कि कार्यप्रमण्डल मधेपुरा अन्तर्गत MR (3054) under New Maintenance Policy- 2018 योजना के पथ में पूर्ण कराये गये कार्यों का भुगतान हेतु अधियाचना विहित प्रपत्र में तैयार कर आवश्यक कार्रवाई हेतु समर्पित की जाती है।

सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

अनु०- 1. अधियाचना विहित प्रपत्र में।

2. Recorder IRI की प्रतिहस्ताक्षरित प्रति।

विष्णुसभाजन

12/6/24

(ई० विद्यानन्द प्रसाद)
कार्यपालक अभियंता,

12/6/24

Form GFR 19- A
(See Government of India's Decision (I) below Rule - 150)
Form of Utilization Certificate upto the month of 12.06.2024
New Maintenance Policy 2018

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs)	Amount Received (in lacs)	Particulars
1	New Maintenance Policy 2018	Letter No 56 Dated 12.08.2020 Letter No 86 Dated 11.12.2020	Rs 211.66000 Vide Letter No :- 74 Dated 03.06.2024	Certified that out of RS 12271.69349 lacs of grants in aid sanctioned during the Years up to 2024-25 in favour of Executive Engineer, RWD Works Division Madhepura under this Department, a sum of Rs 11965.23481 lacs has been utilized for the purpose of New_MR Scheme remaining 306.45868 unutilized at the end of the period under report.
		Total :	211.66000	


Certified and verified myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercised :-

- i Works have been supervised by Executive Engineer/ Superintending Engineer.
- ii Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii Construction material have been tested.
- iv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- v All other codal formalities have been observed.

Physical Progress achieved :-

- i Construction of Road works.
- ii Construction of CD works


D.A.O. 12/6/24
RWD works Division
Madhepura


12/6/24
Executive Engineer
RWD works Division
Madhepura


12/6/24

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Madhepura

Sl.No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative		Agreement Amount (in		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percent age	Previous Total Allocated Amount (I Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (In lac)	Remarks
					Length (In Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)										
1	RM/MA/MAD/24/001	REO Road Nilo Bhagat to sharma tola	21004713012	6120 / 04.12.2023	0.7	36.735	27.23539	6.7205	53 MBD /2023-2024 14.03.2024	13.12.2024	11.06.2024	3558.42	25mm	5%	0.00	0.00	27.23000	Complete
2	RM/MA/MAD/24/001	Construction of Road From NH 107 To Birniya Tola	21004713022	6120 / 04.12.2023	0.945	52.307	41.93996	8.5583	53 MBD /2023-2024 14.03.2024	13.12.2024	11.06.2024	3509.88	25mm	5%	0.00	0.00	41.93000	Complete

G.P.T.
12/06/24
Divisional Accounts Officer
RWD Works Division
Madhepura

S.P.
12/06/24
Executive Engineer
RWD Works Division
Madhepura

Name Of Road :-RFO Road Nilo Bhagat to sharma tola Name Of Contractor :- BARUN KUMAR

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	CATEGORY ROAD	IRI	Latitude	Longitude	Event
11/06/24	18:15:42	35	0.1	280	10.1	3800	G	3899	25.89126	86.740362	Normal
11/06/24	18:16:17	35	0.1	220	10.1	3200	G	3318	25.89123	86.739382	Normal
11/06/24	18:16:17	35	0.1	190	20.2	3200	G	3845	25.89134	86.738422	Normal
11/06/24	18:19:30	35	0.1	130	20.2	3300	G	3258	25.89126	86.740362	Normal
11/06/24	18:20:09	35	0.1	150	10.1	3500	G	3522	25.89085	86.737717	Normal
11/06/24	18:22:10	35	0.1	260	10.1	3600	G	3772	25.8904	86.70705	Culvert
11/06/24	18:23:1	35	0.1	130	10.1	3300	G	3295	25.89016	86.73603	Normal
AVERAGE IRI								3558.42			

$Y = 0 * X^2 + 1.136 * X - 181$
 $X = 1300$
 $Y = 1295$
 (R) RURAL ROAD
 Good Average Poor
 <4000 $4001-5000$ >5001


SEARCHED
 11/06/2024
 JTC

CHECKED
 11/06/24
 AC

11/06/24
 12/06/24

File : F:\STECO-USB-GPS V1_1\18050845.Xls, Section No. :35, Eqn : $Y = 0 * X^2 + 1.136 * X - 181$

Name of Customer :BARUN KUMAR, Name of Work/ Road :REO Road Nilo Bhagat to sharma tola, Lab Job number



~~SGD/09~~
~~21/10/20~~
ST

~~Sharma~~
~~11/10/20~~
ST

~~Sharma~~
~~12/10/20~~
ST