

HEALING PRACTICE SUPPLEMENT PYESY
PIT-10-2000 SUPPLEMENT 17752 1214
Schedule XIV-Form No. 132

HATHESHA KAMBER SINGH DIVISION

~~THAT~~ ~~LOCH~~ & ~~AND~~ SUB-DIVISION

THESY-SL

HEASUPPLEMENT BOOK

HE-10-430

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>1st Year Maintenance</u>					
Name of Road -	Madipur Pakari				
Sketch of road	from Pakari to Pakari Sikar				
with Tolg.					
Date of start -	16/3/21				
Date of completion -					
Agency -					
Agreement No -					
Date of measurement -	16/3/21 to 16/3/21				

<u>Measurement</u>					
Q1 Making up kerbs/shoulders, stopping excess soil from the shoulder surfaces to achieve level etc - - etc					
1 x 4.00 x	1.00 =				4.00
4 x 30.00 x	0.65 =				78.00
1 x 30.00 x	0.80 =				24.00
					108.00
					106.00
Q2 Road signs maintenance - - etc					
0.385 x 50%	=	0.192	km		
Q3 Maintenance of 200 m and kerbs					
1 x 0.385 km	=	0.385	km		
<u>Grand Total</u>					
12/9/23					
12/9/23					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			H	7017	= ∞
Add L. cess 1%			H	70	= ∞
Add G.S.T		12%.	H	842	= ∞
Add S.F			H	105	= ∞
			H	8036	= ∞
less for below 1.		72%.	H	138	= ∞
			H,	7896	= ∞
Paid		S			
1219123		12-9-23		COP	
M-		M		Signature	
				20-12-23	