

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					1st year maintenance bill
					Abstract of cost.
(11)	Redwoodim 30 Rain				
	Cut	---	---	---	at,
116.676m ²	Qty idex (69) TMB				
	CR 392.44/m ²				R 45788 =
(212)	Making up of 3 corni/				
	shoulders	---	---	---	at,
643.0m ²	Qty idex (69) TMB				
	CR 53.69/m ²				R 34523 =
(317)	Maintenance of 20				
	wood Hp culvert				at,
6.0m ²	Qty idex (69) TMB				
	CR 1104.25/each				R 6626 =
(4112)	Cutting of branches of				
	tree	---	---	---	at,
4.0m ²	Qty idex (70) TMB				
	CR 114.93/each				R 460 =
(21)	Cutting of shrubs				
	from Roadway				at,
18.0m ²	Qty idex (70) TMB				
	CR 6.42/each				R 116 =
(512)	White washing on				
	parapet walls				
103.878m ²	Qty idex (70) TMB				
	CR 15.63/m ²				R 1624 =
					R 89137 =
					R 8914 =
	Less 104. m per 100 ft				R 80223 =

Continuation

C.O



Scanned with OKEN Scanner

end year main: bill.

Abstract of cost.

(1/1) Restoration of Rain

cut - - - - - a₁

140.62m² Hydrap (73) TMB

CRs 392.47/m² Rs 55206 = 0

(2/2) Making up of Berms/

Shoulders - - - - - a₂

(864.0m²) Hydrap (73) TMB

Limit 806.62m² CRs 53.69/m² Rs 43311 = 2

(3/2) Mainthg of work

Hplur at - - - a₃

6.0 Ha) Hydrap (73) TMB

CRs 1104.35/each Rs 6626 = 0

(4/8) Mainthg of Road Signls.

2.2901cm Hydrap (73) TMB

CRs 1036.35/1cm Rs 24772 =

Continuation

C.D

Rs 107620 = 0

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.f	Rs	107620 =
(5/9) Main of 200m stone					
2.390km divider (74) Tms					
Ch 604.36/Km - Rs					1444 =
(6/11) cutting of boundary of					
field - - - - -					
4.00km divider (74) Tms					
Ch 114.93/each - Rs					460 =
(22) Cutting of shrubs from					
Road Way - - - - -					
18.00km divider (74) Tms					
Ch 6.42/each - Rs					116 =
					Rs 109640 =
Less 10% as per Agt (F)					Rs 10964 =
					Rs 98676 =
<u>Material statement</u>					
G.W. - 140.673m					
M 105-12-22 R A 21/2/22 AV					