

1<sup>st</sup> year maintenance  
New: Plant. of Rose from  
Harpur Uhat Mahabalesh  
menelis. to Diche  
Dunge Asthan.  
Agency - Sri, Raju Kusnerjha  
Agri. No - 22 SPD / 2021-22  
D.O.S - 21.05.2021  
D.O.C - 20.05.2022  
Actual doc - 17.05.23  
(i) Restoration of Raincult -  
 $10 \times 2.50 \times 0.85 \times 0.35 = \text{₹.44}$



| Particulars                 | Details of actual measurement |                       |    |         | Contents of area |
|-----------------------------|-------------------------------|-----------------------|----|---------|------------------|
|                             | No.                           | L.                    | B. | D.      |                  |
| <u>Abstract of Cost</u>     |                               |                       |    |         |                  |
| (1) Restoration of Raincut- |                               |                       |    |         |                  |
| Qty vide THB-P-41           |                               |                       |    |         |                  |
| 1.77.20 m <sup>3</sup>      | @ R.                          | 394.30/m <sup>3</sup> | R. | 30440 = |                  |
| (2) Maint. of earthen sh... |                               |                       |    |         |                  |
| Qty vide THB-P-41           |                               |                       |    |         |                  |
| 1.428.91 m <sup>2</sup>     | @ R.                          | 8.53/m <sup>2</sup>   | R. | 25104 = |                  |
| (3) Maint. of Road sign-    |                               |                       |    |         |                  |
| Qty vide THB-P-41           |                               |                       |    |         |                  |
| 1.525 km                    | @ R.                          | 1104.57/km            | R. | 1684 =  |                  |
| (4) Cutting of Branches-    |                               |                       |    |         |                  |
| Qty vide THB-P-41           |                               |                       |    |         |                  |
| 800 Nos                     | @ R.                          | 113.99/each           | R. | 912 =   |                  |
| (5) Topping of gully-       |                               |                       |    |         |                  |
| Qty vide THB-P-41           |                               |                       |    |         |                  |
| 1.1028.38 m <sup>2</sup>    | @ R.                          | 2.33/m <sup>2</sup>   | R. | 2398 =  |                  |
|                             |                               |                       | R. | 60538 = |                  |
| Accl Gully 12%.             | @ R.                          |                       |    | 7265 =  |                  |
| Accl Gully 1%.              | @ R.                          |                       |    | 605 =   |                  |
| Accl S. Fee                 | @ R.                          |                       |    | 403 =   |                  |
|                             |                               |                       | R. | 68811 = |                  |
| Less Below (5.57%)          | @ R.                          |                       |    | 3833 =  |                  |
|                             |                               |                       | R. | 64978 = |                  |
| 105/29                      |                               |                       |    |         |                  |
| JE                          |                               |                       |    |         |                  |
| 16                          |                               |                       |    |         |                  |

22/05/24  
JE  
16