

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

N/w: Maintenance of Road from

Mahasyattan Buraiga Mukhya

Sadak to Dimmerpur utari

Simon Bhanpur

Agency: Sri, Janak Kishore Rai.

Ag. No. 24(SBD)/2020-21

D.O.W. 10.08.2020

D.O.C. 09.08.2021

Actual D.O.C. - 20.05.2023

① Restoration of Ramchak —


RHS	4 x	3.50 x	1.05 x	0.35 =	6.12
	6 x	2.75 x	0.95 x	0.30 =	4.70
	5 x	3.00 x	1.00 x	0.30 =	4.50
	3 x	2.90 x	0.90 x	0.35 =	2.74

RHS	7 x	4.0 x	1.10 x	0.30 =	9.24
	10 x	4.15 x	0.95 x	0.35 =	13.99
	15 x	3.50 x	1.00 x	0.35 =	18.37
	25 x	3.25 x	1.35 x	0.30 =	32.91
LHS	20 x	3.75 x	1.15 x	0.25 =	30.19
	12 x	2.90 x	1.00 x	0.30 =	10.44
	11 x	2.80 x	0.95 x	0.35 =	10.24
	10 x	3.00 x	0.80 x	0.35 =	8.40
					151.64 m ³

② Making up of Berms —

RHS	15 x	10.00 x	0.90	135.00
	20 x	12.00 x	0.85	204.00
	17 x	8.00 x	0.80	108.80

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					Bf R 153812:
Less Area cut + L. cut (134) G/R					17396:
Area s. free					G/R 1052:
					R, 152260:
Len. Below (15.12.4.)					G/R 23022
					R 129288:
 20/05/29 JE					
Yak q/c - 282.60 m ³ q/c - 1.866 m ² S.S. - 0.147 m R.I. - 0.014 m					


20/05/29
JE