

2nd year maintenance

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w: Maintenance of Road from Mukhya Sadak HM/14 to Kumber tele.					
Agency: Sri Nihal Kumar.					
Agri. No: 20 SB/2021-22					
D.O.W: 30.06.2021					
D.O.C: 07.03.2022					
Actual D.O.C: 30.03.2022					

Details -

① Restoration of Raincut -

RHS	7x	3.25x	1.15x	0.30 =	7.85
	5x	2.50x	1.20x	0.35 =	5.25
	8x	3.15x	1.00x	0.35 =	8.82

LHS	6x	2.75x	1.10x	0.30 =	5.44
	4x	3.50x	1.05x	0.30 =	4.41
	9x	2.65x	1.10x	0.35 =	7.87
	6x	3.00x	1.00x	0.30 =	5.40
	2x	2.15x	0.95x	0.35 =	1.43
					<u>46.47 m³</u>

② Making up of Berms -

8x	10.00x	0.90	→	72.00
5x	7.00x	0.85	→	29.75
10x	5.00x	0.95	→	47.50
02x	6.00x	0.80	→	09.60
				<u>158.85 m²</u>

③ Ret. Retain with ...

