



कार्यपालक अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य प्रमंडल मुंगेर



पत्रांक—535
मो0-8986915296

दिनांक—10/05/2024
ई मेल — ee.reomunger@gmail.com

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, मुंगेर।

सेवा में,

नोडल पदाधिकारी,
नई अनुरक्षण नीति 2018" (3054-MR)
ग्रामीण कार्य विभाग, बिहार पटना।

विषय :— शीर्ष MR(3054) "नई अनुरक्षण नीति 2018" योजनान्तर्गत पथ के निर्माण में
संवेदक के विपत्र भुगतान हेतु राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि शीर्ष MR(3054) "नई अनुरक्षण
नीति 2018" योजनान्तर्गत पथ:—

1. NH-80 To Anandi Yadav House In Ram Nagar Chhoti Lagma Under Hemjapur Panchyat
2. Repair of Dhobiya Kota Aproaching road of Bangalwa Panchayat Dharhara block में Surface कार्य पूर्ण के भुगतान हेतु आवंटन की अधियाचना विहित प्रपत्र में भर कर की जाती है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अनु0:—यथोक्त।

विश्वासभाजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल मुंगेर

Requisition Formate for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Munger

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/MT/MTU N/23/0007	NH-80 To Anandi Yadav House In Ram Nagar Chhidi Laguna Under Heanapur Panchayat	20803704022	Letter No-2328 Date-04.05.2023	0.350	23.32000	21.11233	2.73339	9-MBD-2023-24	18-Jul-24		3057	-	-	0.00000	0.00000	20.08237	0.350 km Fully PCC Road
2	RM/MT/MTU N/23/0008	Repair of Dhobiya Koti Approaching road of Bangabwa Panchayat Dhartara block	20803708161	Letter No-2328 Date-04.05.2023	0.300	54.53000	49.887	7.42966	5-MBD-2023-24	11-Jun-24		2955	-	-	0.00000	0.00000	49.22683	0.300 km Fully PCC Road
Total =																	70.0920	

- Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
- Up-to-date Physical Progress has been uploaded in MIS.

[Signature]
10/05

[Signature]
10/05/2024
Executive Engineer
RWD, Works Division, Munger

**EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION,
Munger**

FROM GFR 19 - A

(See Government of India's Decision (I) below Rule - 150)
Form of Utilisation Certificate upto the month of May-2024

Name of the Head :- MR (New Maintenance Policy 2018) Fund

Month:- 10-May-2024

Sl. No.	Name of Scheme	Sanctioned No./ Date	Amount Received (in Lacs Rs.)	Particulars
1	2	4	5	6
1	Construction of Rural Roads under (NEW Maintenance Policy 2018) Fund	Vide Up to Letter No.47 WE dt. 25.02.2024	4221.68995	Certified that out of Rs. 4221.68995 Lacs received during the year 2019-20 in favour of Executive Engineer R.W.D. Works Division, Munger, Bihar a sum of Rs 4116.72972 Lacs has been utilized for the purpose of MR (<u>New Maintenance Policy 2018</u>) Fund Schemes as given in the margin for which it was sanctioned and Surrender Amount Rs 104.96023 Lacs and that the balance of Rs 0.00000 Lacs remaining un-utilized at the end of the period under.
	Total -		4221.68995	


- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose fo


Kind of Checks Exercised :-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test checks conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formatities have been observed.

3 **Physical Progress achieved :-**

- Construction of Road Works.
- Construction of CD. Works.


10/05
Sr. Divisional Accounts Officer
Rural Works Department
Works Division, Munger


10/5/2024
Executive Engineer
Rural Works Department
Works Division, Munger


10/05/2024

Name of Road - Repair of Dhobiya Kota Approaching road of Bangalwa Panchayat Dharhara block

Date	Time	Section No.	Length in km	Bumps in m/m	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
10/5/24	8:22:0	15	0.1	240	10.1	2400	2435	G	25.20376	86.4383	Normal
10/5/24	8:22:0	15	0.1	260	20.2	2600	2615	G	25.2034	86.43816	Normal
10/5/24	8:22:0	15	0.1	270	20.2	2700	2745	G	25.2032	86.43811	Normal
10/5/24	8:22:0	15	0.1	250	20.2	2500	2575	G	25.20289	86.43803	Normal
10/5/24	8:23:0	15	0.1	310	20.2	3100	3125	G	25.2024	86.43795	Normal
10/5/24	8:23:0	15	0.1	340	30.3	3400	3425	G	25.20231	86.43791	Normal
10/5/24	8:23:0	15	0.1	360	20.2	3600	3625	G	25.20177	86.43778	Normal
10/5/24	8:23:0	15	0.1	320	30.3	3200	3215	G	25.20138	86.43773	Normal
10/5/24	8:24:0	15	0.1	280	10.1	2800	2835	G	25.20099	86.43773	Normal

$$Y = 0 * X^2 + 1.021 * X - 31.77$$

$$X = 0$$

$$Y = -32$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

10/05/24
A. E.

10/05/24
A. E.

10/05/24

Executive Engineer
RWD Works Division
Munger

Name of Customer :	Madan Kumar
Name of Work/ Road :	Repair of Dhoby's Kot's Approach
Lab Job number :	15
Date :	10-05-2024
Section No. :	15


Test Date :	10-05-2024	Road Name :	Repair of Dhoby's Kot's Approach
Machine No. :	385	Road Type :	(R) RURAL ROAD
Start S No. :		Side :	
Start E No. :		Interval :	
Weather :		UIV Range :	1435 To 5000
Start Location :		Dist Range :	0 To 1
End Location :		Equation :	$Y = 0 \cdot X^2 + 1.021 \cdot X - 31.77$

Print Generate Report and Graph

Redraw Graph

Map View

File : C:\Users\BPRDA2\Documents\BPRDA2\10050900.xlsx Section No. : 15. Egn : $Y = 0 \cdot X^2 + 1.021 \cdot X - 31.77$
 Name of Customer : Madan Kumar, Name of Work/ Road : Repair of Dhoby's Kot's Approaching road of Bangalwa



[Signature]
10/5/24

[Signature]
10/5/24
A.P.

[Signature]
10/5/24
Executive Engineer
RWD Works Division Munger