

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Restoration of rain Cuts in all kinds of Soil Avail- able on Site as silty sandy, clay or morum as per specification and direction of E19, Quantity vide Page - (57) of T.M.B. $246.18 m^3 @ Rs. 380.58/m^3 = 9369$					
2. Making of up Berms, Shoulders, stripping excess Soil from the Shoulders, Surface to achieve Level etc. Quantity vide Page - (58) of T.M.B. $1070.62 m^2$ $@ Rs. 58.37/m^2 = Rs. 6249$					
3. Maintenance of Pottema mix Seal surface Road - Repair to pot hole mix Seal Sustaining using bitumen Binder 13.2mm to 0.075mm. Quantity vide Page - (57) of T. M.B. - $148.05 m^2$ $@ Rs. 310.86/m^2 = Rs. 46023$ C. Rs. 202206					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				BIFRS.	202206=
4. Maintenance of CD works as per specification.					
Quantity vide Rate - (57) -					
4.0 NO. @ RS. 1117.0 each RS					4468=
5. Maintenance of Slab type culvert as per specification Quantity vide rate - (57).					
1.0 NO. @ RS. 2309.04 each RS					2309=
6. Maintenance of Road edge vide Rate - (57) - 0.49 KM.					
@ RS. 1074.51/KM RS					525=
7. Laid down channel of stone and km Stone vide Rate (57).					
0.61 KM @ RS. 651.44/KM RS					398=
8. Cutting of branches of tree and shrubs vide Rate - (57) - 7 NO. @ RS. 106.52 each RS					746=
9. Cutting of shrubs from road way vide Rate - (57) -					
of T.M.B. 32 NO. @ RS. 6.54 each RS					209=
10. Whet washing of CD work vide rate - (58) - 80 M ² @ RS. 16.65/M ² RS					1332=
					RS. 2,12,193
Add 1-1. Labour cess					RS. 2,12,22=
Add 12-1. G.S.T					RS. 25463=
					RS. 2,39,778=
Less 1.75% below					(@ RS. 4196=)
					RS. 235,582=
					CAP
					20/09/23
					P.T.O.