

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			P&L-		
2x 25m x 1.5 x 0.30					22.50m ³ 49.50m ³
2. Maintenance of earthen shoulder					
Filling with fresh soil etc.					
2x 30m x 0.90					= 54.0m
2x 25 x 0.50					= 25
2x 24m x 1.0					= 48.0m ²
2x 2x 25 x 1.0					= 100m ²
2x 20 x 1.0					= 40m ²
					267.0m ²
3. Maintenance of bottom					

max soil surface road.

$$10 \times 5 \times 0.45m = 22.50m^2$$

4. Maintenance of culvert - 3 No.

5. Maintenance of 200m and

$$KM 8th - 1x 1.171KM = 1.171KM$$

<u>ms</u>	<u>Shrikant</u>	<u>C.P.</u>
15/9/23	20/10/23	28/10/23
J.E.	A.E.	

ABSTRACT of C&S-

1. Restoration of rain cuts

Overlying vide K&S - (10)

49.50m³ worked - 48.09m³

@ Rs. 404.06/m³ Rs. 19431.0

Continuation

Rs. 19431.0

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
1. Restoration of drain					
Cut with 80 cm width					
Quantity vide Rate - (12)					
of T.M.B. - 55.80m ²					
@ Rs. 401.06/m ² Rs. 2254					
2. Maintenance of earthen shoulder					
(Filling with fresh selected soil)					
Quantity vide Rate - (40) of					
T.M.B. - 316.0m ²					
@ Rs. 60.28/m ² Rs. 19048					
3. Maintenance of road surface					
mix soil surface -					
Quantity vide Rate - (46).					
44m ² @ Rs. 212.25/m ² Rs. 9339					
4. Maintenance of sub-type					
Culvert - Quantity vide Rate					
- (46) - 3 No. @ Rs. 2394.90 each Rs. 7185					
5. Maintenance of Road Sign					
Quantity vide Rate - (47) - 1.17km @ Rs. 1104.15/km Rs. 1295					
6. Maintenance of 20M and 10M					
Stone vide Rate - (48) - 1.17km					
@ Rs. 748.22/km Rs. 875					
Rs. 60286					
Add 1.1. labour cess on 121.61 Rs. 7837					
Rs. 68123					
Less 15% @ 8% below					
As per Agreement. Rs. 10253					
Rs. 57870					
S. Kumar					
3/2/24					
Continuation					
15/02/24					