

35
Sch. XLV Form No. 134

Particulars	Details of Actual Measurement			Contents of area
	No.	A.	B.	
M/V No. -	1.	B.	C.	Contents of area
Constituents of area				
Barishapuri				
Masjid to Barishapuri				

Agency:- Ram Vishwas Ray

Ketmoharai Barishapuri

Dumka, Jharkhand

App. no:- SB/013 of 2019-2020

1) Restoration of culvert

Qty. vide TMB
Page - 33

82.47 m³

@ Rs. 380.58/m³

Rs. 31386=00

2) Making up Berms/Shoulder
stripping excess soil

Qty. vide TMB
Page - 34

342.36 m²

@ Rs. 58.32/m²

Rs. 19984=0

3) Repair to pot holes using bitumen binders

Qty. vide TMB
Page - 34

47.58 m²

@ Rs. 298.81/m²

Rs. 14217=0

4) Maintenance of Hume pipe culvert

Qty. vide TMB
Page - 34

4.00 nos.

@ Rs. 1117.00/nos.

Rs. 4468=00

5) Maintenance of slab culvert

Qty. vide TMB
Page - 34

2.00 nos.

@ Rs. 2309.64/nos.

Rs. 4618=0

Continuation

Sch. XLV-Form No. 134

Material statement

- 1) $\text{epw}:$ - 82.47 m^3
@ Rs. $23.71 / \text{m}^3$

2) $\text{chips}:$ - 1.28 m^3
@ Rs. $479.28 / \text{m}^3$

3) Bitumen: - 111.34 K

~~✓ 3/6/2022
ME~~

~~eh~~
25/06/2021
15-

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF LIST.</u>					
1. Restoration of rain cuts With Soil macadam as per specification. Overlay Wide Rate - (39), 91.56m ²					
	@ Rs. 380.58 / m ²				Rs. 34846/-
2. Making of Beams and Shoulder, Stopping of Cess from the Shoulder Overlay Wide Rate - (39),					
	398.90m ² @ Rs. 58.37 / m ²				Rs. 23,284
3. Patch repairs over pot holes with 20mm, m/s Seal Surface Overlay Wide Rate - (40) - 70.73 M ²					
	@ Rs. 279.96 / M ²				Rs. 19802/-
4. Maintenance of Bit umen mix Seal Surface using Bitumen Binder Overlay Wide Rate - (40),					
	70.73 M ² @ Rs. 298.81 / M ²				Rs. 21,135/-
5. Maintenance of CP work H.P.e. Wide Rate - (40) - 4 NO.					
	@ Rs. 1117.0 each				Rs. 4468/-
					C) Rs. 49067.2 103535

Continuation

Sch. XLV-Form No. 134 43

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				P.S. P.R.P.	103535- 9900/-
6. Maintenance of Slab					
Culvert wide Rate - (3.5).					
2-0410. @ RS. 2300. per cu.m. Rs. 14618/-					
7. Maintenance of Road					
Sights Country wide Rate					
- (40) . 0.20 Km					
@ RS. 1074.31/KM RS. 172/-					
8. Maintenance of Quarry					
and Limestone wide Rate					
- (49) - 0.20 Km					
@ RS. 6.51.44/KM RS. 130.00					
9. cutting of branches of tree					
and shrubs Country wide					
Rate - (40) - 320-					
@ RS. 106.52 each RS. 320.00					
10. cutting of shrubs from					
Road with Country wide					
(49) 11m.					
@ RS. 6.54 each RS. 725.00					
11. Trimming of grass and					
Weeds Country wide					
Rate - (41) - 26 m ²					
@ RS. 2.18/m ² RS. 57.00					
12. Road Marking in B.T.					
Surface Country wide					
- (41) - 203 m ²					
@ RS. 850.93/m ² RS. 172739.00					
Continuation C.O.R. 281,643:-					

Sch. XLV-Form No. 134

Continuation