

Abstract of cast

49

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of Rain cuts					
B-VTHB P47(1)	=	21.12	m ³		
c R- 380 = 58/m ² — R.					8038=00
(2) Maintenance of earthen					
shoulder					
B-VTHB P47(2)	=	76.65	m ²		
c R- 58.37/m ² — R.					4474=0
(3) Maintenance of bituminous					
surface road					
(iv) Repair to Pot hole					
B-VTHB P48(3)	=	14.23	m ²		
c R- 289.62/m ² — R.					412.1=00
(v) Patch repair:-					
B-VTHB P48(2)	=	14.23	m ²		
c R- 308 = 49/m ² — R.					4390=00
(vi) Pmm. and laying Road					
Marking (BT portion)					
B-VTHB P48(4)	=	50.00	m ²		
c R- 850 = 93/m ² — R.					42546=0
(vii) Pmm and laying Road					
Marking (ce portion)					
B-VTHB P48(5)	=	262.00	m ²		
c R- 947.57/m ² — R.					248263=0
					R. 3,11,832=0
					/

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	P.F	P1-3	11.8	3.2 = 00	
Add 1. f. labour cost (.)		31	18 = 00		
Add 12. f. GST	(+)	37.4	20 = 00		
	P1. 352,	370 = 00			
SF RS =		102	= 00		
	RS2	352	472 = 00		
Rs 1000/-					
06/12/2019					
OE					
C.R					
Aud					
15/05/2019					
Material statement					
(i) Soil - 27.33 m ³ @ 239/m = 648 =					
(ii) chips - 0.77 m ³ @ 499.29/m ³ = 389 =					
(iii) sand - 0.77 m ³				RS = 1017 = 00	
(iv) bitumen - 0.068 MT					
Rs 1000/-					
06/12/2019					
OE					
Ramdas					
15/05/2019					
Continuation					

Continuation