

Heo Yaelav Tella to konbuaq
nd. Tgshad Masim. Wanga SC
Shedule XLV Form No. 134.

M.M. 04/3

E. E. R. C. D. P. gaudi

DIVISION

(SC)

gauri

SUB-DIVISION

Measurement Book

M.B.NC-1021


 10/11/2020
 10/11/2020
 10/11/2020

1st year Maintenance
 n/w. Maintenance of Road
 from Heroyadav Tola To
 Kom Pur
 Agency - Md Irshad Nabi
 Ag No - 26/SBD/HMGS/2020-21
 actual dt of Completion -

D Restoration of drains -			
4x	2.50	1.60	4.80 m ³
5x	2.75	1.40	6.60 m ³
3x	3.10	1.70	4.74 m ³
4x	2.50	1.40	4.20 m ³
3x	3.25	1.70	5.05 m ³

Continuation

25.39 m³

Sch. XLV-Form No. 134

Sch. XLV Form No. 134					
Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
② Maintenance of gutter on shedden.					
	27	30.00	1.05		126.00 M ²
	28	15.00	0.60		18.00 M ²
					144.00 M ²
③ Patch repair over bituminous surf. - 20 m P.M.C.					
	04	1.60	1.30		8.32 M ²
	07	1.25	1.45		1.81 M ²
					10.13 M ²
④ Maintenance of H.P. culverts - 03 x 1.5 -					
Admission 20/2/23 J.C. Admission 20/2/23 A.F.					
Material statement					
01) F.W.		40.64 M ³			
②) S/C.R.P.S.		0.27 M ³			
③) Bitumen		0.019 MT			
Admission 20/2/23 J.C. Admission 20/2/23 A.F.					

ABSTRACT OF COST

31

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Rectification of 29m c/b					
work done.					
25.39 M ³ (M.B.P 29)					
				at 395.76/m ³	10048.0
② Maintenance of earthen					
shoulder					
144.00 M ² (M.B.P 30)					
				at 59.28/m ²	8536.0
③ Patch repair over bitu					
minum surface					
10.13 M ² (M.B.P 30)					
				at 171.57/m ²	1737.0
④ Maintenance of C.D					
work done					
03 M ³ (M.B.P 30)					
				at 1130.67/M	3392.0
				R	23713.0
Add 12% GST + L.C (+1)					3083.0
				R	26796.0
Less 18.20 / As Per 18.17					4877.0
				R	21919.0
Approved 20/2/23 J.E				Approved 20/2/23 A.E	