

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सासाराम-1

Email ID:- ee.rwd.sasaram1@gmail.com

Mob:- 8986915310

पत्रांक..... 1219 अक्ष
सासाराम/दिनांक..... 20/5/2024

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

सेवामें,

नोडल पदाधिकारी (MR 3054)
ग्रामीणकार्यविभाग
पटना, बिहार

विषय :- नई अनुस्क्षण नीति-2018MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध आवंटन उपलब्ध कराने के संबंध में।

महाषय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुस्क्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु0 :- यथोक्त।

विश्वासराज
(इ० समन्वय पंडित)
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सासाराम-1

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)

Form of Utilization Certificate up to May 2024

Sl.No	Name of Scheme	Sanction No.&Date With Amount (In lace Rs.)	Amount Received (In lace Rs.)	Particulars
1	Construction of Rural roads Under MR	New Maintenance Policy-2018 MR (3054) BRRDA PATNA	14010.45620	Certified that out of Rs. 14010.45620 lakh of grants-in-aid sanctioned during the years 2021-24 In favor of EE, RWD works division Sasaram-1 sum of Rs 14010.45620 lakh has been utilized for the purpose of MR (3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs.0.00000 lakh remaining unutilized at the end of the period under report.
Total:			14010.45620	

2. Certified that I have satisfied my self that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
 - Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
 - Construction materials have been tested.
 - Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
 - All other caudal formalities have been observed.
3. **Physical Progress achieved:-**
- Construction of Road Works.
 - Construction of CD works.

Divisional Accounts Officer
R.W.D, works Division
Sasaram-1

Executive Engineer
R.W.D, works Division
Sasaram-1

OFFICE OF EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, SASARAM-1

Registration Format for Scheme Head- MR(3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division:- Sasaram-1

Name of Works Division:- Sasaram-1																		
Sl no.	Batch No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative Approval (AA)		Amount of Rectification with Surface Renewal (in Lakh)	Initial 5 Year Agreement Amount (in Lakh)	Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Previous Total Allocated Amount (in lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition done against work (in Lakh)	Remarks	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/RO/5 AS/24/00 01	NH to to Nirma Gorpa via Karam Akasi	10301002331	6120 04.12.2023	3.55	190.714	105.30369	25.07104	20/MBD/2 023-24 & 16/03/2024	15/12/2024	0	2337	25	5	0.00000	0.00000	58.65192	

Divisional Accounts Officer
Rural Works Department,
Sasaram-1

Executive Engineer
Rural Works Department
Sasaram-1

Name of Road:- NH-2 Nima Gotpa Via karma Akashi

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
16/5/24	11:23:25	66	0.1	200	10.1	2000	2215	G	25.3940	84.58097	Normal
16/5/24	11:23:35	66	0.1	210	10.1	2100	2515	G	25.3792	84.59057	Normal
16/5/24	11:24:30	66	0.1	180	20.2	1800	2215	G	25.3492	84.60302	Normal
16/5/24	11:25:0	66	0.1	180	10.1	1800	2415	G	25.3293	84.61328	Culvert
16/5/24	11:25:11	66	0.1	190	20.2	1900	2315	G	25.3042	84.62305	Normal
16/5/24	11:25:20	66	0.1	180	20.2	1800	2215	G	25.2845	84.63282	Normal
16/5/24	11:25:46	66	0.1	190	20.2	1900	2315	G	25.2637	84.64258	Curve
16/5/24	11:26:0	66	0.1	200	20.2	2000	2415	G	25.2140	84.64898	Normal
16/5/24	11:26:12	66	0.1	210	20.2	2100	2515	G	25.2028	84.65892	Normal
16/5/24	11:26:21	66	0.1	180	20.2	1800	2215	G	25.1968	84.66902	Normal
16/5/24	11:26:36	66	0.1	190	20.2	1900	2315	G	25.1770	84.67862	Normal
16/5/24	11:26:36	66	0.1	190	20.2	1900	2315	G	25.1770	84.67862	Normal
16/5/24	11:27:0	66	0.1	170	20.2	1700	2215	G	25.1470	84.68787	Curve
16/5/24	11:27:11	66	0.1	180	20.2	1800	2215	G	25.1240	84.69763	Normal
16/5/24	11:27:32	66	0.1	190	20.2	1900	2315	G	25.9720	84.7074	Normal
16/5/24	11:28:7	66	0.1	200	10.1	2000	2415	G	25.5700	84.7200	Speed Breaker
16/5/24	11:28:42	66	0.1	190	20.2	1900	2315	G	24.999648	84.71532	Normal
16/5/24	11:29:0	66	0.1	180	20.2	1800	2215	G	24.998747	84.71278	Normal
16/5/24	11:29:13	66	0.1	200	20.2	2000	2415	G	24.99786	84.71143	Normal
16/5/24	11:29:18	66	0.1	210	20.2	2100	2515	G	24.99699	84.70975	Normal
16/5/24	11:29:31	66	0.1	200	20.2	2000	2415	G	24.99623	84.7106	Curve
16/5/24	11:30:0	66	0.1	210	20.2	2100	2515	G	24.996147	84.72003	Normal
16/5/24	11:31:5	66	0.1	190	20.2	1900	2315	G	24.995422	84.72238	Curve
Average IRI							2337				

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2000$$

$$Y = 2415$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

16/05/24
J.E/Sasaram

16/05/24
AE

Executive Engineer
Rural Work's Department
Work Division, Sasaram-1


Name of Customer: Kuman Lalita Singh
 Name of Work: NH-2 Nima Goipa Via Karma Akashi
 Lab Job number: 66
 Date: 16-05-2024
 Section No.: 66

Test Date: 16-05-2024
 Machine No: 478
 Start S No: 03
 Start E No: 24
 Weather: Normal
 UV Range: 1115 To 4000 mm/km
 Dist Range: 0 To 23
 Equation: $Y = 0 \cdot X^2 + 1000 \cdot X + 415.2$
 Road Name: Nima Goipa Via Karma Akashi
 Road Type: (R) RURAL ROAD
 Side: Sasaram
 Interval: 1000

Print Generate Report and Graph

File F:\Bump Machine report\New MR Road 2024\Kuman Lalita\16-05-2024 Lalita.xls. Section No: 66. Eqn: Y = 0

Name of Customer: Kuman Lalita Singh. Name of Work: Road NH-2 Nima Goipa Via Karma Akashi. Lab Job



16-05-24
J.E./Sharon

16/05/24
at

16/05/24

Name of Road:- NH-2 Nima Gotpa Via karma Akashi

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
16/5/24	11:38:0	67	in km	in mm	Rate	mm/km	mm/km	ROAD			
16/5/24	11:38:20	67	210	10.1	2100	2215	2215	G	25.9130	84.72407	Normal
16/5/24	11:39:0	67	180	10.1	1800	2215	2215	G	25.6620	84.7340	Normal
16/5/24	11:40:6	67	200	10.1	2000	2415	2415	G	25.4320	84.74343	Normal
16/5/24	11:41:0	67	190	10.1	1900	2315	2315	G	24.999837	84.7507	Normal
16/5/24	11:41:17	67	190	10.1	1900	2315	2315	G	24.999615	84.7611	Normal
16/5/24	11:41:17	67	210	10.1	2100	2515	2515	G	24.99957	84.77053	Normal
16/5/24	11:43:0	67	190	10.1	1900	2315	2315	G	24.999372	84.78063	Normal
16/5/24	11:47:8	67	180	10.1	1800	2515	2515	G	24.999402	84.77827	Curve
16/5/24	11:47:22	67	200	10.1	2000	2415	2415	G	24.999402	84.77827	Curve
Average IRI											
2359											

Y = 0 * X + 2 + 1.000 * X + 415.2
X = 2000
Y = 2415
(R) RURAL ROAD
Good Average Poor
<4000 4001-5000 >5001


Executive Engineer
Rural Work's Department
Work Division, Sasaram-1
16/05/24

16/05/24
16/05/24

16-05-24
J E / Sasaram

Name of Customer: Kumar Lalita Singh
 Name of Work/ 2 Nima Gopu Via Karma Akashi
 Road: 67
 Lab Job number: 67
 Date: 16-05-2024
 Section No.: 67

Test Date: 16-05-2024
 Machine No: 478
 Start S No: 25
 Start E No: 33
 Weather: Normal
 Start Location: 5913.8472407
 End Location: 9402.8477827
 Equation: $Y = 0.0 \times X^2 + 1.000 \times X + 415.2$
 Dist Range: 0 To 1 Interval: 0.1
 UV Range: 1215 To 4000 mm/km
 Side: Sasaram
 Road Type: (R) RURAL ROAD
 Road Name: Nima Gopu Via Karma Akashi



16/05/24
AC

16/05/24
AC

16-05-24
J. P. Sharma

Name of Road:- NH-2 Nima Gotpa Via karma Akashi

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
16/5/24	11:50:15	68	0.1	200	10.1	2000	2415	G	24.999542	84.73988	Normal
16/5/24	11:51:0	68	0.1	210	20.2	2100	2515	G	24.998648	84.73703	Normal
16/5/24	11:51:15	68	0.1	180	20.2	1800	2215	G	24.997738	84.73380	Speed Breaker
16/5/24	11:51:26	68	0.1	190	20.2	1900	2315	G	24.996672	84.73030	Normal
16/5/24	11:52:36	68	0.1	200	10.1	2000	2415	G	25.65273	83.948163	Normal
Average IRI											
2375											
Good											
Average											
Poor											
<4000											
4001-5000 >5001											
(R) RURAL ROAD											
Y = 2415											
X = 2000											
Y = 0 * X ^ 2 + 1.000 * X + 415.2											

Executive Engineer
Rural Works Department
Work Division, Sasaram-1
16/05/24

16/05/24
At

16-05-24
Jt. Engineer
Sasaram


Name of Customer :	Kumar Lalita Singh
Name of Work :	2 Nima Goipa Via karme Akashi
Road :	68
Lab Job number :	68
Date :	16-05-2024
Section No. :	68

Test Date :	16-05-2024
Machine No :	478
Start S No :	34
Start E No :	38
Weather :	Normal
Start Location :	9542.8473988
End Location :	273.83948163
Equation :	$Y = 0.4 \times X^2 + 1.000 \times X + 415.2$
Road Name :	Nima Goipa Via karme Akashi
Road Type :	(R) RURAL ROAD
Side :	Sasarem
Interval :	
Ultrasonic Range :	1215 To 4000
Ultrasonic Range :	1000 mm/km
Dist Range :	0 To 0.5
Dist Range :	0.1
Dist Range :	1000 m

Print Generate Report and Graph

Redraw Graph

Map View



16-05-2024
J. T. Bhattacharya

16/05/24
AC

16/05/24
J. T. Bhattacharya