

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>1st Year Maintenance</u>					
Name of work — T.O.4					
to Yadav Tola.					
Authority — E.E. R.W.D.					
Dalsing sarai					
Agency — Vipin Kr.					
Sahani					
Agg. No. — 23/SBD/2018-19					
Date of start — 07/08/2018.					
Date of comp — 23/7/2019					
① Restoration of rain cuts					
with soil —					
$37 \times 1.84 \times 1.96 \times 0.3 = 40.03 \text{ m}^3$					
② Earthen shoulder —					
$30 \times 6.50 \times 1.11 = 216.45 \text{ m}^2$					
③ Patch repair over bituminous					
surface with M.S.S. —					
$9 \times 1.4 \times 1.22 = 15.37 \text{ m}^2$					
④ Maintenance of H.P.					
culvert —					
$1 \times 3 \text{ Nos} = 3 \text{ Nos.}$					

B.F. Amount = 31717 = ∞

28

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Qty vide P.No - (25) of TMB					
2 Nos			@ 104.48		
			= 209 = ∞		
8) Cutting of shrubs from roadway —					
Qty vide P.No - (25) of TMB					
7 Nos			@ 6.42		
			= 45 = ∞		
9) Trimming of grass and weeds —					
Qty vide P.No - (25) of TMB					
3.06 m ²			@ 2.14		
			= 7 = ∞		
10) White washing of parapet walls —					
Qty vide P.No - (26) of TMB					
61.92 m ²			@ 16.15		
			= 1000 = ∞		
			= 32978 = ∞		
Less 10% Below			= (-) 3298 = ∞		
			= 29680 = ∞		
Sum 201720 Continuation					