

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name & Work) Bank path in					
Muchhba Dhamna					
EA → Pindi bazaar side					
Age → 08 BTM MUKT DATE EXECUTIVE CHAUSAL					
ADD.O.C. → 12-04-2022					
(1) Reservoir of earth cut					
$15 \times 5 \times 0.9 \times 0.30 = 20.25$					
$3 \times 10 \times 0.60 \times 0.30 = 5.40$					
$7 \times 5 \times 0.60 \times 0.30 = 6.30$					
$T = 31.95$					
cum					
Weight $T = 31.95$ cum					
(2) making up Beam shoulder stripping excess -					
$15 \times 10 \times 0.90 = 135.00$					
$4 \times 20 \times 0.75 = 60.00$					
$25 \times 10 \times 0.90 = 225.00$					
$2 \times 30 \times 0.60 = 36.00$					
$13 \times 10 \times 0.60 = 78.00$					
$T = 534.00$					
sqm					
(3) patch repair on alcoves filled pot holes -					
$3.0 \times 0.90 \times 0.60 = 16.20$					
$T = 17.53$ sqm					

Approved of cost

① Restoration of rail cuts

wide item on (1) p/72

31-39 cm @ 407.90

127.97-00

(2) Making up of words

shoulder

Wine item no. 2 10/92

53 4.0 mm ♂ 60-58

~~\$ 32350.00~~

(6) poet's reader can already

~~Filled rat hole~~

Vdo Ref ID: S P/72

~~14.53 cm 8/25/03~~

= 3720.00

Sch. XLV-Form No. 134