

2010 year Maintenance bill.

33

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/A:- Maintenance of Road from					
Mullim tal (SH-55) to					
Mullim tal.					
Agency:- M/s Jai Mata Bhagwati					
Construction & Co.					
Agg No:- 02/ (B.D) MMGSY/NDB-20-21					
Agg Rate:- 0.01/- as per Agg-					
D.O.S:- 24-02-2021					
A.D.O.C:- 12-12-2021					
Recorded on:					
(1/1) Restoration of Rain					
Cut - - - - -					
15 Nos $3.80 \times 0.90 \times 0.30 = 15.39 m^3$					
8 Nos $2.10 \times 0.80 \times 0.30 = 4.032 m^3$					
6 Nos $1.90 \times 1.00 \times 0.30 = 3.42 m^3$					
10 Nos $2.40 \times 0.950 \times 0.30 = 6.84 m^3$					
18 Nos $1.00 \times 0.700 \times 0.30 = 3.78 m^3$					
7 Nos $2.0 \times 0.750 \times 0.30 = 3.15 m^3$					
					36.612 m ³
(2) Making up of Broom					
Shoulders - - - - -					
9 Nos $8.00 \times 0.850 = 61.20 m^2$					
6 Nos $7.00 \times 6.00 = 25.20 m^2$					
10 Nos $5.0 \times 0.90 = 45.0 m^2$					
8 Nos $2.0 \times 1.00 = 16.0 m^2$					
					147.40 m ²
					/

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.F.R		30931 = 0
(22)			Cutting of shoulder		
			from Roadway - 4,		
5.0 Nos			Atyridap (34) TmB		
			CR 6.94 each		R 35 = 0
(8/13)			Maintenance of already		
			planted trees - 4,		
40.0 Nos			Atyridap (34) TmB		
			CR 690.0 each		R 27600 = 0
					R 58566 = 0
			Add 12% GST (+)		R 7028 = 0
			Add 1% LC (+)		R 586 = 0
			Add S. fee (+)		R 475 = 0

					R 66655 = 0
					(less 0.01 H. as per Agt) R 7 = 0
					R 66648 = 0
					<i>Asuredh</i>
					22-3-24
					<i>18-01-24</i>
					<i>18</i>

Pravin
22/3/24

Executive Engineer
RWD Works Division
Manjhaul Bakhari