

MMSYISC - 1046 to Bara - 1.710 Km

Ag. No - 9 SRD / 21-22

Schedule XLV-Form No. 134

Name of Agency :- Satyendra Kumar Yadavendra

Sherghati

DIVISION

~~Rana Chetti~~ Amas

SUB-DIVISION

Measurement Book

1364

1st Year Maintenance bill

60

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
10 ①					
Name of work -	Lays to P.A.R.A				
Agency -	Satyendra Kumar Yadav				
Agreement No -	09813/21-22				
Item ①	Restoration of Rain cuts/				
	Berms with soil				
	10	5.10	1.20	0.300	18.36m ³
	8	4.20	1.15	0.280	9.66m ³
	9	3.90	1.25	0.300	13.16m ³
	11	4.50	1.10	0.300	16.33m ³
	15	1.90	1.20	0.300	10.26m ³
	11	5.15	1.15	0.300	19.54m ³
					87.31
					Unit - 86.57m ³
Item ②	Making up of Berms/				
	Shoulder				
	10	4.10	1.15	-	47.15m ²
	12	5.20	1.20	-	74.88m ²
	11	4.80	1.25	-	66.00m ²
	13	5.50	1.15	-	82.22m ²
	11	4.50	1.10	-	54.45m ²
	9	6.10	1.20	-	65.88
	8	5.80	1.15	-	53.36m ²
	10	3.60	1.00	-	36.00m ²
					479.94m ²
Item ③	Repair of Pot holes				
	filled with 75mm with				

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item (9) Maintenance of Road					
Sigh - 1.71 km					
Item (10) Maintenance of 200m and 1km. Phone					
- 1.71 km					
Item (11) cutting of branches of tree and shrubs					
- 4 m					
Item (12) cutting of shrubs from roadway.					
1 x 9.00 = 9.00 m					
1 x 8.10 = 8.10 m					
				17.10 m	

Item (13) Trimming of grass and weeds					
2 x 20 x 30 x 1.20					1440 m ²
2 x 30 x 30 x 1.25					2250 m ²
1 x 5 x 30 x 1.00					150 m ²
					3840 m
Item (14) White washing of parapet wall					
2 x 4 x 6.0 x 1.6					76.8 m ²
2 x 2 x 6.0 x 0.40					9.6 m ²
1 x 4 x 2.6 x 0.40					4.16
1 x 2 x 2.6 x 0.40					2.08 m ²
1 x 4 x 6.6 x 0.40					10.56 m ²
1 x 2 x 6.6 x 0.40					5.28 m
					108.48 m

Continuation

A. K. K. K.
28/08/24
a

ABSTRACT OF COST

63

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1/18.1a) Restoration of Rainwater					
V.T.M.B.P.N.-(60)					
item (1) —				86.52 m ³	
@ 404.06/m ³ —					34979.2
(2/15.2d) Making up of Berms					
Shoulder					
V.T.M.B.P.N.-(60)					
item (2) —				479.94 m ²	
@ 60.28/m ² —					28931.20
(3/15.3d) Repair of pot holes					
filled with 75 mm width					
V.T.M.B.P.N.-(60)					
item (3) —				0.12 m ²	
@ 9668.06/m ² —					1160.2
(4/15.3ii) Patch repair over					
pot holes					
V.T.M.B.P.N.-(60)					
item (4) —				40.08 m ²	
@ 280.64/m ² —					10046.50
(5/15.3iii) Patch repair over					
bituminous surface					
V.T.M.B.P.N.-(60)					
item (5) —				40.08 m ²	
@ 288.48/m ² —					16245.50
(6/15.3iv) Filling of cracks					
and joints					
V.T.M.B.P.N.-(60)					
item (6) —				1680 m	
@ 3.85/m —					6468.00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(7/15.20) Maintenance of road works (H.P. culvert)					
V.T.M.B.P.No. - (61)					
item (7) - 4 H					
Q 1166.58/10					4666.2
(8/15.21) Maintenance of road works (Slab culvert)					
V.T.M.B.P.No. - (61)					
item (8) - 2 H					
Q 2394.96/10					4790.2
(9/15.9) Maintenance of road sign					
V.T.M.B.P.No. - (62)					
item (9) - 1.71 H					
Q 1104.59/10					1889.2
(10/15.11) Maintenance of road and landscape					
V.T.M.B.P.No. - (62)					
item (10) - 1.71 H					
Q 643.12/10					1100.2
(11/15.12) Cutting of branches of tree and shrubs					
V.T.M.B.P.No. - (62)					
item (11) - 4 H					
Q 113.64/10					455.2
(12/15.12) Cutting of shrubs for road work					

Continuation

Continuation