

कार्यपालक अभियंता का कार्यालय  
ग्रामीण कार्य विभाग, कार्य प्रमंडल-शिवहर।

Mob No.-8986915416

Email ID-eerwdsheohar@gmail.com

पत्रांक:- 1732 /शिवहर

दिनांक:- 25/10/24

प्रेषक,

ई० चन्दन कुमार भार्गव,  
कार्यपालक अभियंता।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,  
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय :-MR (3054) नई अनुरक्षण नीति 2018 के तहत पथ के अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक के संबंध में सूचित करना है कि कार्य प्रमंडल-शिवहर के अंतर्गत MR (3054) New Maintenance Policy 2018 के तहत करायें गये कार्यों के भुगतान हेतु राशि की अधियाचना विहित प्रपत्र में समर्पित की जा रही है।

अनु०- यथोक्त।

विश्वासभाजन

25/10/24  
कार्यपालक अभियंता,  
ग्रामीण कार्य विभाग,  
कार्य प्रमंडल, शिवहर  
25.10.2024

FROM GER 19-A

[ See Government of India's Decision (I) below reule-150]  
Form of Utilization Certificate for the month of up to October 2024

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacsRs.)	Amount Received (in lacsRs.)	Particulars
1	Construction of Rural Roads Under MR-3054 New Maintenance Policy 2018	BRRDA Lt. No. 103 Date- 01.10.2024	4435.83671/-	Certified that out of Rs-4435.83671 Lakh of grants in aid sanctioned during the Years-2024 in favour of Executive Engineer, RWD Works Division, Sheohar Rs-3913.64536 Lakh Has been utilized for the purpose of MR-3054 New Maintenance Policy 2018 schemes as given in the margin for which it was sanctioned and that the balance of Rs-522.19135 lakh remaining unutilized at the end of the period under report.
Total:-			4435.83671/-	

2. Certified that I have satisfied my self that conditions on which the grants –in- aid was sanctioned have been duly fulfilled /are beingfulfilled and I have ,exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of Checks exercise.

- (i) Work have been supervised by of Executive Engineer/ Superintending Engineer.
- (ii) periodical inspection has been conducted by of Executive Engineer/ Superintending Engineer.
- (iii) Construction materials have been tested.
- (iv) Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/  
Executive Engineer.

3 All other codal formalities.

- (i) Physical progress achieyed.
- (ii) Construction of Road works.
- (iii) constructionof CD Works .

25.10.2024

Executive Engineer  
R.W.D .Works Division,  
Sheohar.

Division Format for Scheme Head-MR (3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division-Sheohar.																			
Sl. No.	Package No	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Length (in km)	Administrative Approval					Agreement No. Date	Date of Completion as per agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allowed Amount (in lakh)	Up to Date expenditure as per MIS (in Lakh)	Requition against work done (in lakh)	Remarks
						Amount (in lakh)	5 Years Routine Maintenance (in lakh)	Initial Rectification with Surfaccer Renewal (in Lakh)	5 Years Routine Maintenance (in lakh)	Agreement Amount (in Lakh)									
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	MR-N/2023-24 Sheohar/03	Bohra Middle School to Islampur tola	31608113002	6120/04.12.2023	0.790	28.53600	8.80900	29.58044	8.86368	MBD/MR-3054/02 of 2024-25 16.08.2024	15.05.2025	3398	25	5%	0	0	29.58000	Completed	
1	MR-N/2023-24 Sheohar/03	Nayagaon Harijan Tola Jahanpur Siman se to Jahanpur via Badub Sahab SC Tola	31608113003	6120/04.12.2023	0.770	38.45200	5.73700	39.82185	5.74110	MBD/MR-3054/02 of 2024-25 16.08.2024	15.05.2025	3554.25	25	5%	0	0	39.82000	Completed	
Total						66.98800	14.54600	69.40229	14.60478						0	0	69.40000		

1. Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
2. Up - to date Physical Progress has been uploaded in MIS.
3. Certificate enclosed

Executive Engineer,  
RWD, Works Div. Sheohar  
25.10.2024

Name of the Road-Naya Gaon Harizan Tola Jahanpur Sima Se to Jahangirpur via Badub Saheb SC Tola  
Contractor Name-Indrajeet Kumar

Length-0.770 KM

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	UIV	CATEGORY ROAD	IRI	Latitude	Longitude	Event	Y = 0 * X ^ 2 + 1.136 * X + 132.5
25/10/24	7:47:56	20	0.1	260	10.1	2600	3086 G	4.13	26.5075	85.223872	Normal	X = 2900	
25/10/24	7:48:23	20	0.1	280	20.2	2800	3313 G	4.4	26.5066	85.223838	Normal	Y = 3426	
25/10/24	7:49:2	20	0.1	300	10.1	3000	3540 G	4.66	26.50618	85.223163	Curve		
25/10/24	7:49:46	20	0.1	320	20.2	3200	3767 G	4.93	26.50565	85.22271	Normal		
25/10/24	7:49:34	20	0.1	310	10.1	3100	3654 G	4.8	26.50471	85.222473	Curve	(R) RURAL ROAD	
25/10/24	7:50:34	20	0.1	330	30.3	3300	3881 G	4.6	26.50388	85.222153	Normal	Good	Average
25/10/24	7:51:9	20	0.1	320	20.2	3200	3767 G	4.93	26.5031	85.22168	Normal	<4000	4001-5000
25/10/24	7:51:48	20	0.1	290	10.1	2900	3426 G	4.53	26.50287	85.220958	Normal		Poor
									IRI	28434			
									AVG. IRI	3554.25			

*[Signature]*  
25/10/2024  
JF

*[Signature]*  
25-10-2024  
JF

*[Signature]*  
25/10/24





Name of Customer : Indrajeet Kumar  
 Name of Work : Naya Gaon Harizan Tola Jahan  
 Road :  
 Lab Job number : 148  
 Date : 25-10-2024  
 Section No. : 20

Test Date : 25-10-2024  
 Machine No : 423  
 Start S No : NAYA GAON  
 Start E No : BADUB SAHE  
 Weather : NORMAL  
 Start Location : 0.00  
 End Location : 0.770  
 Road Name : Naya Gaon Harizan Tola Jaha  
 Road Type : (R) RURAL ROAD  
 Side :  
 UIV Range : 2086 To 5000 Interval 1000 mm/km  
 Dist Range : 0 To 0.9 Interval 0.1 \* 1000 m  
 Equation :  $Y = 0 * X^2 + 1.136 * X + 132.5$

Print


Generate Report and Graph

Redraw Graph

Map View

File : C:\Users\deli\Desktop\25100753.Xls. Section No. : 20. Egn :  $Y = 0 * X^2 + 1.136 * X + 132.5$

Name of Customer : Indrajeet Kumar, Name of Work/ Road : Naya Gaon Harizan Tola Jahanpur Sime Se to



25/10/24  
 JE

B-bhushan  
 25-10-2024  
 AE


25/10/24

**कार्यपालक अभियंता का कार्यालय**  
**ग्रामीण कार्य विभाग, कार्य प्रमंडल शिवहर।**  
**प्रमाण-पत्र**


विभागीय आदेशानुसार सत्यापित किया जाता है कि शीर्ष 3054 (नई अनुरक्षण नीति 2018) अंतर्गत नयागाँव हरिजन टोला जहाँगीरपुर सिमान से जहाँगीरपुर भाया बदुब साहेब हाउस पथ, प्रोजेक्ट आई०डी०- 31608113003 का मरम्मत कार्य की जाँच 100 प्रतिशत संबंधित कनीय अभियंता, 50 प्रतिशत संबंधित सहायक अभियंता एवं 10 प्रतिशत कार्यपालक अभियंता द्वारा किया गया है।



कनीय अभियंता,  
ग्रामीण कार्य विभाग,  
कार्य प्रशाखा, डुमरी कटसरी।

  
25-10-2024

सहायक अभियंता,  
ग्रामीण कार्य विभाग,  
कार्य अवर प्रमंडल, डुमरी कटसरी।

  
25/10/24

कार्यपालक अभियंता,  
ग्रामीण कार्य विभाग,  
कार्य प्रमंडल, शिवहर।