

① Restoration of parent/

Boxes with soil. medium

12	$\times 2.25$	$\times 0.90$	$\times 0.30$	$= 7.29 \text{ m}^3$
8	$\times 2.60$	$\times 1.00$	$\times 0.30$	$= 6.24 \text{ "}$
6	$\times 3.15$	$\times 1.10$	$\times 0.20$	$= 4.16 \text{ "}$
12	$\times 3.30$	$\times 1.00$	$\times 0.20$	$= 7.92 \text{ "}$
9	$\times 2.65$	$\times 1.20$	$\times 0.30$	$= 8.59 \text{ "}$
				34.20 m^3

Continuation

Scanned with CamScanner

Particulars	Details of actual measurement				Contents of Area
	No.	L.	B.	H.	
RECEIPT OF COT. & 1000					
YONG. 1000000 1500					
① Distribution of Channels					
Revised with settlement					
54.50 m ² vide TMB P. No. 26					
@ R. 551.03/m ²				R.	12605.00
② Making up of Berms					
shoulder stripping					
excels 1000 m ²					
193.92 m ² vide TMB P. No. 27					
@ R. 56.54/m ²				R.	10960.00
③ Maint. of op. works					
02 Nos. vide TMB P. No. 27					
@ R. 1130.67/each				R.	2261.34
④ Maint. of final Sign					
0.07 km vide TMB P. No. 27					
@ R. 1090.73/km				R.	76.35
⑤ Maint. of view and km stone					
0.09 km vide TMB P. No. 27					
@ R. 482.56/km				R.	43.43
⑥ White washing of parapet					
walls of 0.9 m ² and					
from double.					

Continuation

