

07
Road Name - Dargapatti to Singh Tola

(M.M.B.S.C.)
Shedule XLV Form No. 134.

Subaul

MBNB-1571

DIVISION

Subaul

SUB-DIVISION

Agreement No - 20/580/22-23

below-D-25/-

Agreement Value - 8801275 = 0.

Measurement Book

MBNB-1571

Name - Rajan Kumar Singh.

1st Year Maint. Bill

49

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work:- Const. of Road					
from Dora/Pathi to Singh					
to/a.					
Agency:- Rajan Kumar Singh					
Agreement No:- 20/SB/2022-2028					
Agreement Road:-					
Date of Start:- 12-05-2022					
Date of Completion:- 11-05-2028					
Muzo Division, Gubani					
KTHI Muzo Department					
EXCHAS EN/14661					

1st Yr Maintenance Bill

1.) Restoration of Raincuts					
$2 \times 15m \times 0.7 \times 0.35 = 7.35 m^3$					
$4 \times 10m \times 0.4 \times 0.20 = 3.20 m^3$					
$4 \times 10m \times 0.6 \times 0.55 = 13.20 m^3$					
$2 \times 15m \times 0.7 \times 0.45 = 9.45 m^3$					
$2 \times 15m \times 0.7 \times 0.35 = 7.35 m^3$					
$2 \times 15m \times 0.7 \times 0.45 = 9.45 m^3$					
$2 \times 15m \times 0.7 \times 0.35 = 7.35 m^3$					
$2 \times 15m \times 0.7 \times 0.35 = 7.35 m^3$					
$2 \times 10m \times 0.4 \times 0.20 = 1.60 m^3$					
<u>58.45</u>					
2.) Making up of Berms/Shoulders					
$6 \times 15m \times 0.35 = 31.50 m^2$					
$4 \times 20m \times 0.30 = 24.00 m^2$					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Material Statement</u>					
1) E/W =					
		@	23.78		
					
<u>Abstract of Cost</u>					
Restoration of Raincote					
Qty = 58.22					Side Fmb P = 49
		@	361.75		Rs = 21061 = 00
Making of Bums / Shoulders					
Qty = 323.44					Side Fmb P = 50
		@	53.18		Rs = 17201 = 00
Maintenance of C/Walk (H.P Culvert)					
Qty = 3 Nos					Side Fmb P = 50
		@	1106.59		Rs = 3320 = 00
Maintenance of C/Walk (Stake)					
Qty = 1 Nos					Side Fmb P = 50
		@	2281.87		Rs = 2281 = 00

Continuation