

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- EE RWD Work Division Anarwa

Name of Block/Road :- Jakhot / Matiyari Rahikpur to Damara Path

A. For Road

1. Damage Location/Chainage :- At ch. 2.5 km

2. Damage Length :- 207 mtr

3. Nature of Damage (Length Wise) (i) Breach :- Breach Damage
(ii) Crust Damage :- Crust Damage
(iii) Only Flank Damage :- Flank Damage

whether traffic fully/Partially obstructed :- fully

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick bats, EC bags, local sand, Bamboo etc.

(ii) Equipment/Tools Being Used in Restoration Works :- JCB, Roller, Tractor with trolley

(iii) Restored Length In open Area :- open Area
In habitation Area :-

(iv) If Restoration work done in habitation Area give Reason :-

B. For Bridge (Size of Bridge/Culvert)

(1) Damage Location/Chainage :-

(2) No. of Span Damage :-

(3) Length of Span :-

(4) Nature of Damage (Pier/Abuttment/
Wing Wall/Approach Road Damage) :-

(5) Details of Restoration :-

(i) Material Being Used in Restoration :-

(ii) Equipment/Tools Being Used in Restoration Works :-

(iii) Restored Length :-

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

6/11/24
m

6/11/24

19/11/24
Signature of Inspector
(Official Seal)