INSPECTION REPORT FOR MOTORABLE WORK

WORK WORK	
Name of PIUs: - EE RWD, Work Division Anaria Name of Block/Road: - Jorihat/Bhansia Chank to Dadi Uda A. For Road	
Name of Block/Road: Takit at 1 Changing of 1 1 1 1	
A. For Road	
1. Damage Location/Chainage:- 4.7 以m	
2. Damage Length: 7 m1y	
3 Nature of Domes of	
3. Nature of Damage (Length Wise) (i) Breach:- Breach Samage	
(ii) Clust Dallage: - Cauch (2000 a)	
[[]]]] [] [] [] [] [] [] [] [] [] [] []	
whether traffic fully/Partially obstructed:	
4. Details of Restoration:	
1) Waterial Being Used in Restoration: Brick had FC Brand food of	2
(ii) Material Being Used in Restoration: - Brick bat, Ec Bogs, Sacal Sond Bank (iii) Equipment/Tools Being Used in Restoration Works: - Paller, TCB, Trackor with (iii) Restored Length In open Area:	gra
(iii) Restored Length In open Area:	to
in open Area	
(iv) If Restoration work done in habitation Area give Reason:	
B. For Bridge (Size of Bridge/Culvert)	
(1) Damage Location/Chainage :-	
(2) No. of Span Damage:-	
(3) Length of Span:-	
(4) Nature of Damage (Pier/Abuttment/	
Wing Wall/Approach Road Damage):-	
(5) Details of Restoration:	
(i) Material Being Used in Restoration:-	
(ii) Equipment/Tools Being Used in Restoration Works:-	
(iii) Restored Length:-	
Overall Grade of Postaviti	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory):- Satisfactory	
4	
Den 4 / MILY	
Signature of Inspector	
(Official Seal)	
(- moral boar)	