

Const. & work from Mogdha to NH (Bank of
Baroda) (under MMSy Gen) (UNE. ENG.)

Schedule XLV-Form No. 134

Executive Engineer

P. W. D. (W.) Division

Darbhanga - 2

DIVISION

Tale

SUB-DIVISION

Art. No. 515BD/2020-21

Measurement Book



Sri Om Prakash Yadav

No. 1054

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	ABSTRACT OF COST				
1.	Restoration of Rain cubs/ Berms with soil all comp. vide TMB P. no - 49 9/100 (1) 30.98 m ² @ 414 - 10/m ² → 12829 =				
2.	Making up of Berms/ shoulder with all comp vide TMB P. no - 49 9/100 @ 172.00 m ² → 16280 =				
3.	Maint. of old works in hume pipe culvert all comp vide TMB P. no - 50 9/100 1 No @ 102.80/m ² → 11032 =				
4.	Maint. of Road Signs with all comp - vide TMB P. no - 50 9/100 @ 0.51 km @ 1054.28/km → 53820 =				
5.	Maint. of 200 m x 1 km stone with all comp.				
					Rs. 24,241 =

Nikl
 20/10/23
 ASE
 25/11/24
 Mat. Statement
 1. E/100 — 83. w m3.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	<u>ABSTRACT OF COST</u>				
1.	Restoration of Rain-cuts / Berms with Soil at co - p.				
	vide TMA P.No-53				
	H-① 36.135 m^3				
	at $414.10/\text{m}^3$				$\rightarrow 14964.20$
2.	Making up of Berms / shoulder with co - p.				
	vide TMA P.No-53				
	H-② 200.0 m^2				
	at $56.81/\text{m}^2$				$\rightarrow 11362.20$
3.	Maintenance of C/D works frame pipe Culverts etc.				
	vide TMA P.No-54				
	H-③ 1 No.				
	at $1102.80/\text{No}$				$\rightarrow 1103.20$
4.	White Washing of parapet wall etc				
	vide TMA P.No-54				
	H-④ 20.05 m^2				
	at $16.00/\text{m}^2$				$\rightarrow 321.20$
					<u>27750.20</u>

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5.	Road marking with hot applied thermoplastic Compound on curb.				
	Area vide TMB P. 16.54				
	9/1 (5) 102.0 M ²				
	at 817-22/M ²				833562w
					/
					Rs-1111062w
	less 10% Beto Asphalt				1111200
					B- 9999500
	  11/9/24 Nikhil 10/6/24 JFE				 10/6/24 JFE