

MB No - 33715

MB No - 33715

Schedule XLV-Form No. 134

DIVISION

Purveyor

SUB-DIVISION

K. Nagar

Gowans Infra. Pvt. Ltd.

Measurement Book

MB No - 33715 to 33716

D

GORM

75880

09190557731 (UNION BANK, PUNE)

PUNE

5th Year Maintenance

Abstract of Cost

86

Sch. XI.V-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work - Mast of Road from PMGSY Path to Saopanch Tola					
Area of Tola					
Agency :- Grama Samithi Pvt Ltd.					
Agreement No - 144 SBD/2018-19					
Date of Commencement - 17/12/2018					
Actual Date of Completion - 16/09/19					

(1/1) Restoration of Rain culch

Beams with soil exposure

43.47 M² QVT MBP 81

@ 365.25/M² Rs 15875.00

(2/2) Marking up of Beams
shoulder & stripping excess

soil from shoulder

420.62 M² QVT MBP 82

@ 54.16/M² Rs 22780.00

(3/3) Repair of Pot holes

filled with 75mm WBM

55.66 M² QVT MBP 83

@ 313.01 M²/M² Rs 17422.00

(4/5) Patch Repair over bitu
surface with 20mm mixed sand

55.66 M² QVT MBP 84

P/k1	95-69 ³
chips	52-61 ³
Bituminous	D-106 MT
Emulsion	0.0167 MT
Jan 1/21	
2019/21	
34	