

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरभंगा-1
email-eerwddarbhangal@gmail.com

पत्रांक :- 23448/

लहेरियासराय दिनांक 09/10/2024

प्रेषक,

ई0 कुमार चन्द्रज
कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, दरभंगा-1

सेवा में,

अपर-मुख्य-कार्यपालक-पदाधिकारी,
ग्रामीण कार्य विभाग,
ब्राडा, पटना।

विषय:- **MR New maintenance Policy 2018** योजना से संबंधित कार्यों के भुगतान हेतु आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त बिषयक संबंध में कहना है, कि ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरभंगा-1 में **MR New maintenance Policy 2018** योजना के अंतर्गत चल रहे कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचना पत्र तैयार कर समर्पित किया जाता है।

अतः अनुरोध है, कि आवंटन शीघ्र उपलब्ध कराने की कृपा की जाय, ताकि संवेदक को भुगतान किया जा सके।

अनु0:- यथोक्त विहित प्रपत्र में।

विश्वासभाजन

(ई0 कुमार चन्द्रज)

कार्यपालक अभियंता,

ग्रामीण कार्य विभाग, कार्य प्रमण्डल, दरभंगा-1

191024

09/10/24

09/10/24

FORM GFR 19-A

(See Government of India's Decision (1) below Rule- 150)

Form of Utilization Certificate up to the 04-10-2024

MR 3054 New maintenance Policy 2018

PIU- RWD, Works Division, Darbhanga-1

Sl. No	Name of Scheme	Sanction No. & Date with Amount (In Rs. Lakh)	Amount Received (In Rs. Lakh)	Particulars
1	MR 3054 New maintenance Policy 2018	BRRDA, Patna. Lt No-81 dt.-04.10.2024	1914.02346	Certified that out of Rs. 1914.02346 Lakh (CFMS) received 04.10.2024 In favour of Executive Engineer, RWD work division Darbhanga-1. A sum of Rs 1885.76179 Lakh (CFMS) has been utilized for the purpose of MR 3054 New maintenance Policy 2018 as given in the margin for which it was sanctioned and that the balance of Rs 28.26167 Lakh (CFMS) remaining unutilized at the end of the period under.
	Total		1914.02346	

Certified that I have satisfied myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Constructions materials have tested.
- Measurements have been recorded in the MBs and test check conduction by the Assistant Engineer/ Executive Engineer
- All other codal formalities have been observed.

Physical Progress achieved :-

- Construction of Road Works.
- Construction of CD Works.

Handwritten signature
D. A. O. 09.10.24
R.W.D. Works Division
Darbhanga-1

Handwritten signature
09/10/24
Executive engineer,
R.W.D. Works Division

Darbhanga-1
09/10/24 09.10.24

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : Darbhanga-1

Oct-24

Sl No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (in Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in Lac)	Remarks
					Length (in Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/DA/DAR/24/0005	PHGSY Path se Habibpur Indranagar	31909212042	Lt No.6120 Dt.04.12.2023	0.920	67.898	46.52275	3.79795	11MBD/2024-25 Dt.01.08.2024	30.04.2025		3066	0	0%	0	0.00000	46.05752	PCC Surface
2	RM/DA/DAR/24/0005	T01 Narsara Sima to Ram Tola	31909213023	Lt No.6120 Dt.04.12.2023	0.435	31.924	22.86998	1.79575	11MBD/2024-25 Dt.01.08.2024	30.04.2025		3199	0	0%	0	0.00000	22.64128	PCC Surface
3	RM/DA/DAR/24/0005	Moro REO Road to Hasanpur Sahani Tola	31909212065	Lt No.6120 Dt.04.12.2023	0.300	22.249	16.07777	1.23845	11MBD/2024-25 Dt.01.08.2024	30.04.2025		3161	0	0%	0	0.00000	13.91699	PCC Surface


 D.A.O.
 RWD Works Division
 Darbhanga-1


 Executive Engineer
 RWD Works Division
 Darbhanga-1
 09/10/24

Name of Work:- T01 Narsara Sima to Ram Tola

Agency:- Rakesh Kumar

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	U/V	CATEGORY ROAD	Latitude	Longitude	Event
8/10/24	11:53:41	165	0.1	220	0	2200	2631 G	26.04861	85.80682	Normal	
8/10/24	11:54:0	165	0.1	270	10.1	2700	3199 G	26.04866	85.80675	Normal	
8/10/24	11:54:31	165	0.1	290	20.2	2900	3426 G	26.04841	85.80616	Normal	
8/10/24	11:54:52	165	0.1	300	30.3	3000	3540 G	26.05191	85.80737	Normal	
Average IRI								3199			

$Y = 0 * X^2 + 1.136 * X + 132.5$
 $X = 3000$
 $Y = 3540$
 (R) RURAL ROAD
 Good Average Poor
 <4000 4001-5000 >5001

Chw
 08/10/24
 08/10/24
 08/10/24

08/10/24
 08/10/24
 08/10/24


Name of Customer :	Rakesh Kumar
Name of Work/ Road :	T01 Narsara Sima to Ram Tola
Lab Job number :	
Date :	08-10-2024
Section No.	165

Test Date :	08-10-2024	Road Name :	T01 Narsara Sima to Ram Tola
Machine No :	364	Road Type :	(A) ASPHALTIC
Start S No :		Side :	
Start E No :		Interval	
Weather :		U/V Range :	1631 To 5000 mm/km
Start Location :	T01 Narsara	Dist Range :	0 To 0.5 0.1 * 1000 m
End Location :	Ram Tola	Equation :	test

Print Generate Report and Graph

Redraw Graph

Map View



08/10/2024
Rakesh Kumar