कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमण्डल दरभंगा–1 email-eerwddarbhangal@gmail.com

पत्रांक :- 23 प्राप्तक/

लहेरियासराय दिनांक ... १ १० २०२५

प्रेषक,

ई० कुमार चन्द्रज कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमण्डल, दरभंगा–1

सेवा में,

अपर-मुख्य-कार्यपालक-पदाधिकारी, ग्रामीण कार्य विभाग, ब्राडा, पटना।

विषय:- MR New maintenance Policy 2018 योजना से संबंधित कार्यों के भुगतान हेतु आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त बिषयक संबंध में कहना है, कि ग्रामीण कार्य विभाग, कार्य प्रमंडल दरमंगा—1 में MR New maintenance Policy 2018 योजना के अंतर्गत चल रहे कार्यों के भुगतान हेतु विहित प्रपन्न में अधियाचना पन्न तैयार कर समर्पित किया जाता है। अतः अनुरोध है, कि आवंटन शीघ्र उपलब्ध कराने की कृपा की जाय, ताकि संवेदक को भुगतान किया जा सके।

अनु0:- यथोक्त विहित प्रपत्र में।

(ई० कुमार चन्द्रज) कार्यपालक अभियंता,

ग्रामीण कार्य विभाग, कार्य प्रमण्डल, दरभंगा-1

FORM GFR 19-A

(See Government of India's Decision (1) below Rule- 150)

Form of Utilization Certificate up to the 04-10-2024

MR 3054 New maintenance Policy 2018

PIU- RWD, Works Division, Darbhanga-1

SI. No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Rs. Lakh)	Particulars
1	MR 3054 New maintenance Policy 2018	BRRDA, Patna. Lt No-81 dt04.10.2024	1914.02346	Certified that out of Rs. 1914.02346 Lakh (CFMS) received 04.10.2024 In favour of Executive Engineer, RWD work division Darbhanga-1. A sum of Rs 1885.76179 Lakh (CFMS) has been utilized for the purpose of MR 3054 New maintenance Policy 2018 as given in the margin for which it was sanctioned and that the balance of Rs 28.26167 Lakh (CFMS) remaining unutilized at the end of the period under.
	Total		1914.02346	

Certified that I have satisfied myself that the conditions on which the grants in aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- i. Works haves been supervised by Executive Engineer/ Superintending Engineer.
- ii. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- iii. Constructions materials have tested.
- iv. Measurements have been recorded in the MBs and test check conduction by the Assistant Engineer/ Executive Engineer
- v. All other codal formalities have been observed.

Physical Progress achieved:-

- L Construction of Road Works.
- ii. Construction of CD Works.

R.W.D. Works Division

Darbhanga-1

Executive engineer,

R.W.D. Works Division

Darbhanga-1

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division: Darbhanga-1

u	**	-	-	, P	
RM/DA/DAR/24/0005	RM/DA/DAR/24/0005	RM/DA/DAR/24/9905		Package no	
Moro REO Road to Hasanpur Sahani Tola	T01 Narsara Sima to Ram Tola	PMGSY Path se Habibpur Indranagar	3	Name of Road	
31909212065	31909213023	31909212042	-	Project ID as per MIS	
Lt No.6120 Dt.04.12.2023	Lt No.6120 Dt.04.12.2023	Lt No.6120 Dt.04.12.2023	<i>y</i>	Administrati ve Approval (AA) Letter No. & Date	
0.300	0.435	0.920	•	Length (In Km)	(AA)
22.249	31.924	67.898	7	Amount (in Lac)	A control
16.07777	22.86998	46.52278	os l	luitial Rectification with Surface Renewal (in lac)	Agreement Amount (in Lac)
1.23845	1.79575	3.79795	6	Agreement Uth 5 years Routine No. & Date ral Maintenance (In lac)	ount (in Lac)
11MBD/2024-25 Dt.01.08.2024	11MBD/2024-25 Dt.01.08.2024	11MBD/2024-25 Dt.01.08.2024	10	Agreement No. & Date	
30.04.2025	30.04.2025	30.04.2025	ш	Date of Completion as per Agreement	
			u	Actual Date of Completion	
3161	3199	3066	5	Value of IRI (In mm/km)	
•			ı	Thickness of Bitumen Layer (in mm)	
0%	9.	0%	15	Value of Bitumen Content in percentage	
•		•	16	Previous Total Alloted Amount (In Lac)	
0.00000	0.00000	0,00000	17	expenditure as per MIS (in Lac)	
Ž į	22,64128	46.05752	=	Requisition Against work done (In Inc)	
SSO PCC Surface	PCC Surface	PCC Surface	19	Remarks	

D.A.O G./D.W.
RWD Works Division
Darbhanga-1

Executive Engineer
RWD Works Division
| Darbhangs | Darb 10 12

Oct-24

Name of Work:-Moro REO Road to Hasanpur Sahani Tola

Agency:- Rakesh Kumar

											-
Normal	85.73178	26.07598	G	3199	2700	20.2	270	0.1	203	8/10/24 9: 15: 14	8/10/24
						Deck probabilities					-
Normal	85.73196 N	26.07646	G	3313	2800	10.1	280	0.1	203	8/10/24 9: 14: 13	8/10/24
											-
Vormal	12 85.88315	26.09812	6	2972	2500	1	250	0.1	203	8/10/24 9:13:11	8/10/24
-											
			ROAD	mm/km	mm/km	Rate	in mm	in km	No.		
	-					-	-			-	
Event	Longitude	Latitude	CATEGORY La	丒	OR	Speed	Bumps	Length	Section	Time	Date
							-		-		
				×	VC311 1	TECTICY - Nancoll Ivalia	1000				

Average IRI

3161

Good <4000 (R) RURAL ROAD Y = 3767

X = 3200

 $Y = 0 * X ^2 + 1.136 * X + 132.5$

Average Poor 4001-5000 >5001