

मेरी

ममस्य

Shedule XLV Form No. 134.

DWARPAHRI LALEBAIRD ROAD TO DIVISION

कृष्ण चौक

SUB-DIVISION

Measurement Book

Meena Devi

320 near Maintenance

27

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/W - Dhanpali Lal Bhai's Road to Chaudhary					
Agency - Meena Devi					
Assessment no. 52/5135/MHGY/20-21					
Date of start - 8/11/20					
Actual date of completion - 22/5/21					
Stamp.					
1.) Restoration of drain cut / beam.					
	13	4.50	0.85	0.30	16.24 m ³
	9	3.80	1.00	0.30	11.29 m ³
	2	3.15	1.05	0.30	13.89 m ³
	3	13	1.00	0.30	11.70 m ³
					Total = 53.12 m ³
2.) Make up of beam / skewer					
	4	32	1.10		140.80 m ³
	2	61	1.05		128.10 m ³
					Total = 268.90 m ³
3.) Repair of P.A. hole with 25 mm B.M.					
	4	1.60	1.15	0.075	0.55 m ³
	4	2.10	1.90	0.075	0.74 m ³
					Total = 1.29 m ³
4.) PA repair over P.A. hole with 20 mm M.S.S.					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
13.) White washing of Plaster					
Top - $2 \times 3.60 \times 0.40$					2.88 m^2
Side - $4 \times 3.60 \times 0.60$					8.64 m^2
front - $4 \times 0.40 \times 0.60$					1.92 m^2
					$\text{Total } 13.44 \text{ m}^2$
14.) Maintenance of already planted trees					
2) 7 top.					
2015					
2015					
2015					
<u>Abstract of cost</u>					
1.) Restoration of rain cut/bench					
QV.M. 13 P- 27					53.12 m^3
@ Rs. 386					20512.20
2.) masonry of bench shoulder					
QV.M. 13 P- 27					268.90 m^2
@ Rs. 57256					154782.20
3.) Repair of Put holes with 25 mm B.M					
QV.M. 13 P- 27					1.29 m^3
@ Rs. 10202					13162.20
4.) Put repair used Put holes					
QV.M. 13 P- 28					12.58 m^2
@ Rs. 255277					44962.20

Continuation

Rs. 53648.20

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5) Put separate area bituminous					
surface					
div msp - 28 y 13.58 m					
@ R. 267 = 161 m ² - R					4692 = W
6.) Main of H.P. culvert					
div msp - 28 y 1 no.					
@ R. 1130 = 67 - R					11312 = W
7) Main of road sign					
div msp - 28 y 0.12 km					
@ R. 1077 = 821 km - R					1292 = W
8) Main of km 4200 m					
div msp - 28 y 0.14 km					
@ R. 628 = 241 km - R					882 = W
9.) cutting of branches of trees & shrubs					
div msp - 28 y 2 m					
@ R. 1092741 no. - R					2192 = W
10.) cutting of shrubs from road					
div msp - 28 y 8 m					
@ R. 62231 no. - R					542 = W
11.) Road marking on B.T.					
div msp - 28 y 50.4 m					
@ R. 735244 m ² - R					36772 = W
12) Road marking on C.C.					
div msp - 28 y 110.4 m					
@ R. 835234 m ² - R					91887 = W
13) white marking on kerb					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
QRMNP-282		13.44 m ²			
@ Rp. 17259/m ²					Rp. 23624
14.7 main of already planted of tree.					
QRMNP-282		7.74			
@ Rp. 574200/no.					Rp. 401824
					Rp. 1,92,879
Asal @ 124 Gns. Tt					
14.74					Rp. 250742
					Rp. 2,17,953
Left 104					Rp. 21,7952
					Rp. 1,96,158200

Material statement

- 1) Soil - 80.18 m³
- 2) Stone chips - 2.73 m³
- 3) Emulsion Res. - 16 Kg
- 4) Primum Sg. - 167 kg
- 5) Emulsion Ss1 - 16 kg

(Signature)
21/5/2017
SE