

	No.	L.	B.	D.
<u>2nd year maintenance</u>				
N/w: Maintenance of Road from				
Bhindi to Haujran Tola.				
Agency:	Bhola Kumar.			
D.O.W:	21.09.2021			
Ag. No:	50 SBD/2021-22			
Actual D.O.C:	15.09.2022			

① Restoration of Gullies —

	8	3.15	1.10	0.30	8.32
	11	2.70	0.90	0.30	8.02
	7	2.55	1.25	0.35	7.81
	9	2.20	0.75	0.30	4.46
	12	2.45	0.85	0.35	8.76
	10	2.75	1.10	0.35	10.59
	15	2.15	1.25	0.30	12.09
	14	2.00	0.80	0.30	6.72
	9	3.10	0.70	0.35	6.84
					73.60 m ³

② Making up of Berms to achieve level —

L.W.S	11	5.25	0.75	—	43.31
	9	6.50	0.70	—	40.95
	12	4.50	0.80	—	43.20
R.H.S	10	7.00	0.85	—	59.50
	04	5.00	0.30	—	66.00
					192.96 m ³

③ Repair to pot hole —

	with 75 mm W.B.M.	
4x 2.65 x 1.40	—	14.84

Sch. XLV-Form No. 134					
Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of Cost</u>					
① Restoration of Road -					
Qty with THB R (50)					
= 60.75 m ³ @ R 404.06 / m ³ — R					24547 =
② Making up of Road —					
Qty with THB R (50)					
= 168.75 m ² @ R 60.28 / m ² — R					10172 =
③ Patch repair on RT Surface					
Qty with THB R (51)					
= 23.44 m ² @ R 277.70 / m ² — R					6509 =
④ Maint. of H.P. Canal —					
Qty with THB R (51)					
2.00 m ³ @ R 1166.58 / each — R					2333 =
⑤ Maintenance of drainage					
planked bed —					
Qty with THB R (51)					
50.00 m ³ @ R 690.00 / each — R					34500 =
					R. 78061 =
Adm Cost + Less 13% — R					10148 =
Any S. Fee — R					325 =
					R. 88534 =
Less 2.51 % Below — R					2222 =
					R. 86312 =
Pdt 10/9/2024					
JE					

making
@ 111 = 86.06 m³