

Mizgopus Makh charik to Musliman dafa

①

Schedule XIV-Form No. 134

Memasy (SCS)

MATTAUDDIN HADAK

DIVISION

Memasy (SCS)

SUB-DIVISION

2971

F-14100

MEMORANDUM BOOK

341

ABSTRACT OF COST

1. Restoration of rain cut

With Soil on masonry

Quantity vide Page-(30) of

T.M.B. 42.74 M³ @ RS. 386.14 / M³ = RS. 16504 =

2. Maintenance of earthen

shoulder (filling with fresh

Selected Soil) Quantity vide

Page-(31) of T.M.B. 237.43 M²

@ RS. 57.36 / M² = RS. 13619 =

C. RS. 30123 =

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				13/12/25	30,123.00
3. Maintenance of Bitumen					
max Seal Surface Quantity					
Wide Road - (31) of T.M.B.					
42-40m ² @RS. 272.86/m ² RS. 11569.00					
4. Maintenance of Bitumen					
Surface Road Quantity					
Wide Road - (32) of T.M.B.					
42-40m ² @RS. 279.13/m ² RS. 11835.00					
5. Providing and Laying					
Hot applied thermoplastic					
on road as per specifications					
Quantity Wide Road - (32)					
— 146m ² @RS. 739.82/m ² RS. 108014.00					
6. Maintenance of 200m					
and KM stone. Wide Road - (32)					
of T.M.B. 0.730 KM					
@RS. 726.47/km RS. 530.00					
					RS. 162071.00
Add I-J. Labourcess					RS. 1621.00
Add 12-J. G.S.T.					RS. 19449.00
					RS. 183141.00
<i>[Signature]</i> 15/7/24 J.E. <i>[Signature]</i> 15/7/24 MR CAP <i>[Signature]</i> 24/07/24					

P.T.O.