

5th Year Maintenance

61

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Block -	T01 Dhapz Tla				
To Menidaga					
Agency -	Gosona infra Pvt Ltd.				
Agreement No -	755 SBD/2018-19				
Date of Commencement -	31/12/2018				
Date of Completion :-	27/09/2019				

Record Entry

① Restoration of Rain cwt/ Berms with soil modulus

$2 \times 6.5 \text{ m} \times 0.900 \text{ m} \times 0.30 \text{ m}$	3.51 m^3
$3 \times 5.00 \text{ m} \times 0.35 \text{ m} \times 0.30 \text{ m}$	3.83 m^3
$2 \times 9.00 \text{ m} \times 0.75 \text{ m} \times 0.30 \text{ m}$	4.05 m^3
$2 \times 11.00 \text{ m} \times 0.700 \text{ m} \times 0.300 \text{ m}$	4.62 m^3
$2 \times 9.50 \text{ m} \times 0.800 \text{ m} \times 0.30 \text{ m}$	4.56 m^3
$3 \times 7.5 \text{ m} \times 0.800 \text{ m} \times 0.30 \text{ m}$	5.40 m^3
$2 \times 7.00 \text{ m} \times 0.85 \text{ m} \times 0.300 \text{ m}$	3.57 m^3
$2 \times 10.0 \text{ m} \times 0.75 \text{ m} \times 0.30 \text{ m}$	4.50 m^3
$2 \times 9.0 \text{ m} \times 0.75 \text{ m} \times 0.30 \text{ m}$	4.05 m^3
$3 \times 7.5 \text{ m} \times 0.800 \text{ m} \times 0.30 \text{ m}$	5.40 m^3
$2 \times 9.0 \text{ m} \times 0.75 \text{ m} \times 0.30 \text{ m}$	4.05 m^3
Total - 47.52 m^3	

Particulars	Details of actual measurement	Contents
Sch. XLV-Form No. 134		

Continuation

5th Year Maintenance Cost

Abstract of Cost

65

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work - Tot Dhapi					Tola
Tot Moni plega					
Agency - Groma 2018 Pvt Ltd.					
Agreement No -					715BD/2018-19
Date of Commencement -					31/12/2018
Date of Completion -					27/09/2019

(1/1) Restoration of Raincut/ Berms with soil mosaic					
47.52 m ² @ VT MBP 61					
@ 365.25/m ²					17356.00

(2/2) Moulding up E-roads/Shoulders strip 200g excess soil from shoulders					
429.02 m ² @ VT MBP 62					
@ 54.16/m ²					23235.0

(3/3) Repair of Pot holes filled with 75 mm KLBM					
61.06 m ² @ VT MBP 62					
@ 353.68/m ²					21595.00

(4/4) Patch Repair over bituminous surface with 20 MM mixed seal					
61.06 m ² @ VT MBP 63					
@ 216.65/m ²					13228.00

Continuation

% 75414.00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				b/p	75414.00
(5/9) Maintenance of Road					
8280					
0.12 KM QVT MBP 63					
@ 1087.62/KM					120.00
					141.00
(6/10) Maintenance of 200 M and K.M stone					
0.20 K.M QVT MBP 62					
@ 582.10/K.M					116.00
(7/11) Cutting of berms of tree and surbs					
2 Nos QVT MBP 64					
@ 107.48/each					214.00
(8/11) Cutting of shrubs from Roadway					
6 Nos QVT MBP 64					
@ 6.60/each					39.00
(9/11) Trimming of grass and weeds					
4.05 M ² QVT MBP 64					
@ 2.20 Rs/M ²					9.00
				c/o	75933.00

Continuation

23/09/24

2025/09/10