

मुख्य मंत्री, गौरी, धुपक, गौरी (SC)

प.१३.१०-३४५१

मिथुन-मिथुन मुख्य मंत्री के आदि-गौरी से मरनी-गौरी तक ५५५)

Schedule XLV-Form No. 134

पक्रान्ता-गौरी-२२३८८/२०२१-२२

सर्व-गौरी-गौरी-गौरी-गौरी-गौरी

गौरी-गौरी-गौरी-गौरी-गौरी (गौरी-गौरी)

DIVISION

गौरी-गौरी

SUB-DIVISION

MEASUREMENT BOOK

प.१३.१०-३४५१

2nd year Maintenance

52

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Maintenance of road from Mijhchaliya Mukhya Path ke Ahir Tola to Bharti Tola tak.					
N/Agency - Sri Bihad Kumar Singh					
Agg. No - 22 SBD/2021-2022					
A.D.O.C - 20-09-2022					
Date of Measurement - 21-10-24					
① Restoration of raincuts / Berms with Soilmoorum etc.					
	10	2.7	60	30	$= 4.86 m^3$
	12	3.0	55	30	$= 5.94 m^3$
	13	3.5	65	30	$= 8.872 m^3$
	9	2.5	65	30	$= 4.387 m^3$
	9	3.0	0.60	30	$= 4.86 m^3$
					28.919 _m
					Qty Limit = 28.86 m ³
② Making up of Berms/Shoulder					
	2	6.5	65		$= 8.45 m^3$
	8	5.4	90		$= 38.88 m^3$
	9	9.8	95		$= 83.79 m^3$
					131.12 m ²
					Qty Limit 131.46 m ²
③ Patch repair over B.T. Surface					
	5	1.5	1.7		$= 12.75 m^2$
	6	0.8	1.80		$= 8.64 m^2$

Continuation

21.39 m²

Qty Limit - 21.38 m²

Continuation

Abstract of cost

54

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of raincuts / Berms with soil, m. or km					
TMB/p-52	28.86	@	386.14	=	1143=00
② Making up of Berms/ Shoulder					
TMB/p-52	131.46	@	57.36	=	7540=00
③ Patch repair over B.P. surface					
TMB/p-52	21.38	@	349.01	=	7460=00
④ Maintenance of C/D work (Slab culvert)					
TMB/p-53	1	@	2329.20	=	2329=00
⑤ Maintenance of road lights					
TMB/p-53	0.13	@	1077.82	=	138=00
⑥ Maintenance of 200m and Km stones					
TMB/p-53	0.16	@	628.24	=	101=00
⑦ cutting of branches of trees and shrubs					
TMB/p-53	2	@	109.74	=	219=00
⑧ cutting of shrubs from roadway					
TMB/p-53	6	@	6.73	=	40=00
⑨ Trimming of grass and weeds					
TMB/p-53	3.38	@	2.24	=	8=00
⑩ Maintenance of trees by the road side by mixing = the soil with decayed					
TMB/p-	30	@	674.37	=	20231=00

Continuation Total Rs 49209
=60

4
p-55.

p-24 49209=0

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Less 13.90% below (A) B.					6840=0
			(A) ←		42369=0
add 12% to Tow (A) (+) B.					5084=0
add 1% to cur (A) (+) R.					424=0
Less out R.					47877=0
(forty seven thousand eight hundred seventy seven only)					
P. S. Singh 21/10/24					21/10/24 P. S. Singh 21/10/24 GE

Material Account:

(i) C/W: 48.550 m³

(ii) Stone chips: 0.60 m³

(iii) Bitumen Vh-10: 0.041 MT

Bitumen Account:

	RS-1	SS-1	Vh-10
%P-24.			5.321 MT
TMBP-Consumption 24			4.102 MT
TMBP/P-50 Consumption			0.066 MT
TMBP/Consumption 50			-0.041 MT
Bal.			1.112 MT

P. S. Singh
21/10/24
P.S.

P. S. Singh
21/10/24
P.S.