

Baldeo Mah to. 'ke ghar Madhubani to  
Dumbariya.

277

# Schedule XLV-Form No. 134

mmssy

MMULY-UEV

Bagha-2

DIVISION

Madhubani

SUB-DIVISION

41141

## Measurement Book

Sabir Hussain



4th year maint. bill.  
(m m c s y, sen)

43

Sch. XLV—Form No. 134

| Particulars                                                     | Details of actual measurement |    |    |    | Contents of area |
|-----------------------------------------------------------------|-------------------------------|----|----|----|------------------|
|                                                                 | No.                           | L. | B. | D. |                  |
| ⇒ Name/Work - "Baldar mahato ke Ghar se madhubani to Bamburija" |                               |    |    |    |                  |
| ⇒ Agency - Sabir hussain (west Champaran)                       |                               |    |    |    |                  |
| ⇒ Agreement no. 09 S B D / 2019-20.                             |                               |    |    |    |                  |
| ⇒ Date/Start - 31-08-2019.                                      |                               |    |    |    |                  |
| ⇒ Actual Date/Completion - 06-06-2020                           |                               |    |    |    |                  |
| ⇒ maint. start — 07-06-2020                                     |                               |    |    |    |                  |
| ⇒ maint. period - 07-06-2023 to 06-06-2024 } = 4th year         |                               |    |    |    |                  |
| I/(15-1) — Restoration of Rain                                  |                               |    |    |    |                  |
| Cuts/Berms with soil                                            |                               |    |    |    |                  |
| Moohom — do — do —                                              |                               |    |    |    |                  |

Abstract of Est  
4th year (1st year)

B.S. XIV Form No. 134

| Particulars                                | Details of actual measurement |   |    |    | Contents of area |
|--------------------------------------------|-------------------------------|---|----|----|------------------|
|                                            | No                            | I | II | D. |                  |
| 1/(15.1) - Restoration of path             |                               |   |    |    |                  |
| Cuts/Dorms with soil                       |                               |   |    |    |                  |
| mooring - do - do -                        |                               |   |    |    |                  |
| Qty wide P(43)/TMD = 81.40 m <sup>3</sup>  |                               |   |    |    |                  |
| @ Rs 380.58/m <sup>3</sup>                 |                               |   |    |    | = 30979 = L      |
| 2/(15.2) - making up of material           |                               |   |    |    |                  |
| irregularities on                          |                               |   |    |    |                  |
| Shoulder to the design                     |                               |   |    |    |                  |
| do do                                      |                               |   |    |    |                  |
| Qty wide P(43)/TMD = 249.75 m <sup>2</sup> |                               |   |    |    |                  |
| @ Rs 58.68/m <sup>2</sup>                  |                               |   |    |    | = Rs 14635 = L   |
| 3/(15.5) - maint. of WBM Road              |                               |   |    |    |                  |
| including filling up of                    |                               |   |    |    |                  |
| pot. holes rats &                          |                               |   |    |    |                  |
| do do                                      |                               |   |    |    |                  |
| Qty wide P(44)/TMD = 52.03 m <sup>2</sup>  |                               |   |    |    |                  |
| @ Rs 553.66/m <sup>2</sup>                 |                               |   |    |    | = Rs 28807 = L   |
| 4/(15.3) - II. Patch Repair on             |                               |   |    |    |                  |
| already filled pot holes                   |                               |   |    |    |                  |
| With 75 mm WBM with 20                     |                               |   |    |    |                  |
| mm PMC with seal coat                      |                               |   |    |    |                  |
| do do all up.                              |                               |   |    |    |                  |
| Qty wide P(44)/TMD = 52.03 m <sup>2</sup>  |                               |   |    |    |                  |
| @ Rs 341.26/m <sup>2</sup>                 |                               |   |    |    | = Rs 17756 = L   |
| 5/(15.3) - III. - Repair to pot            |                               |   |    |    |                  |
| holes by removal of                        |                               |   |    |    |                  |
| failed materials, Fin                      |                               |   |    |    |                  |
| ishing of sides clearing                   |                               |   |    |    |                  |
| do do all up.                              |                               |   |    |    |                  |
| Qty wide P(44)/TMD = 52.03 m <sup>2</sup>  |                               |   |    |    |                  |
| @ Rs 358.17/m <sup>2</sup>                 |                               |   |    |    | = Rs 18635 = L   |
| Continuation                               |                               |   |    |    |                  |
|                                            |                               |   |    |    | = Rs 110812 = L  |

| Particulars                                | Details of actual measurement |    |    |    | Contents of area |
|--------------------------------------------|-------------------------------|----|----|----|------------------|
|                                            | No.                           | L. | B. | D. |                  |
| B. & F. Amount                             |                               |    |    |    | = Rs 110812 =    |
| 6/(15.7)-II. maintenance of                |                               |    |    |    |                  |
| slab type Culvert - do -                   |                               |    |    |    |                  |
| 874 wide P(44)/TMB = 1 sh.                 |                               |    |    |    |                  |
| @ Rs 2305.03/each                          |                               |    |    |    | = Rs 2309 =      |
| 7/(15.9)- maint. of Road sign              |                               |    |    |    |                  |
| - do - do -                                |                               |    |    |    |                  |
| 874 wide P(44)/TMB = 0.50 km               |                               |    |    |    |                  |
| @ Rs 1074.51/km                            |                               |    |    |    | = Rs 537 =       |
| 8/(10.1)-I. painting new letters           |                               |    |    |    |                  |
| and figures of army shade                  |                               |    |    |    |                  |
| - do - do - all C/S.                       |                               |    |    |    |                  |
| 874 wide P(45)/TMB = 44 ch                 |                               |    |    |    |                  |
| @ Rs 0.53/cm                               |                               |    |    |    | = Rs 23 =        |
| 9/(15.11) - maint. of 200m 3 km            |                               |    |    |    |                  |
| stone by way of - do -                     |                               |    |    |    |                  |
| 874 wide P(45)/TMB = 1.005 km              |                               |    |    |    |                  |
| @ Rs 729.07/km                             |                               |    |    |    | = Rs 733 =       |
| 10/(15.12)-I. Cutting of branches          |                               |    |    |    |                  |
| of tree and shrubs - do -                  |                               |    |    |    |                  |
| 874 wide P(45)/TMB = 6 nos.                |                               |    |    |    |                  |
| @ Rs 106.52/each                           |                               |    |    |    | = Rs 639 =       |
| 11/(15.12)-II. Cutting of shrubs           |                               |    |    |    |                  |
| from the road way - do -                   |                               |    |    |    |                  |
| 874 wide P(45)/TMB = 13 nos                |                               |    |    |    |                  |
| @ Rs 6.54/each                             |                               |    |    |    | = Rs 85 =        |
| III. Trimming of Grass &                   |                               |    |    |    |                  |
| Do - do - do - all C/S.                    |                               |    |    |    |                  |
| 874 wide P(45)/TMB = 508.78 m <sup>2</sup> |                               |    |    |    |                  |
| @ Rs 2.18/m <sup>2</sup>                   |                               |    |    |    | = Rs 1109 =      |
|                                            |                               |    |    |    | = Rs 116247 =    |

| materials statement       |                        |
|---------------------------|------------------------|
| ① Earth work -            | = 98.51 m <sup>3</sup> |
| ② Stone Aggregates        | = 2.81 m <sup>3</sup>  |
| ③ Coarse Sand             | = 0.62 m <sup>3</sup>  |
| ④ Bitumen emulsion (RS-1) | = 0.026 MT             |
| ⑤ Bitumen (VG-10) (5-90)  | = 0.2227 MT            |

  
 07/06/2014  
 J.F.

  
 08/06/14  
 A.C.

