

4th year maintenance.

62

Sch. XLV—Form No. 134

[illegible]

work done.

④ Restoration of rain cut/benches
with soil mounds --- G/H.

$$4 \times 2.00 \text{ m} \times 0.70 \text{ m} \times 0.30 \text{ m} = 1.68 \text{ m}^3$$

$$2 \times 2.00 \text{ m} \times 0.7 \text{ m} \times 0.30 \text{ m} = 0.84 \text{ m}^3$$

$$5 \times 4.00m \times 0.90m \times 0.30m = 5.40m^3$$

$$8 \times 4.00m \times 0.80m \times 0.30m = 7.68m^3$$

$$12 \times 4.0 \text{ m} \times 0.70 \text{ m} \times 0.30 \text{ m} = 10.08 \text{ m}^3$$

$$6 \times 8.00m \times 0.70m \times 0.20m = 10.08m^3$$

$$11 \times 4.20 \text{ m} \times 0.70 \text{ m} \times 0.30 \text{ m} = 9.702 \text{ m}^3$$

$$8 \times 6.00 \text{ m} \times 0.90 \text{ m} \times 0.30 \text{ m} = 12.96 \text{ m}^3$$

$$58.42 \text{ m}^3$$

② Making up of berms/shoulder stripping excess soil. — 6/1

$$4 \times 4.00 \text{ m} \times 0.80 \text{ m} = 12.8 \text{ m}^2$$

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		7x4.20m	X 0.90m		26.46m ²
		8x4.00m	X 0.90m		28.80m ²
		9x7.00m	X 1.10m		69.30m ²
					137.36m ²
					limit = 137.25m ²
③ Repair over pot holes filled with 25mm WBM X 1.25					
					Qty = 28.59m ²
④ patch repair over pot holes with 20mm premix surfacing material — 6/t					
					Qty = 28.59m ²
⑤ Patch repair over bitum. in old surface with 20mm premix surfacing — 6/t					
					Qty = 28.59m ²
⑥ Maintenance of c/s work. (H.P. culvert)					
					Qty = 2 nos.
⑦ Maintenance of c/s works (slab culvert).					
					Qty = 2 nos
⑧ Maintenance of road sign.					
					Qty = 0.11km
⑨ Maintenance of 200m & km stones					
					Qty = 0.13km
⑩ Cutting of branches of trees and shrubs					
					Qty = 1 nos.

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Cutting of shoulder from road					
				Qty =	4 nos
② Trimming of grass & weed				Qty =	8.00m ²
③ White washing of parapet wall of — E/t				Qty =	21.00m ²
Signature 14.10.24 J.E				Signature 14/10/24 A.E	
ABSTRACT of cost					
① Restoration of raincut/benches with soil masonry — E/t				Qty. vide TMB P (62)	
				in no. ① 58.42 m ³	
				@ Rs 365 = 25/m ³	Rs 21338 = 00
② Making up of benches/shoulder stripping excess soil — E/t				Qty. vide TMB P (62)	
				in no. ② 137.25 m ²	
				@ Rs 54 = 16/m ²	Rs 7433 = 00
③ Repair over pot holes filled with 75mm WBM X 1.25				Qty vide P. ③	
				in no. ③ 28.59 m ²	
				@ Rs. 375 = 57/m ²	Rs 10738 = 00
					% Rs 39509 = 00

Particulars	Details of actual measurement.				Contents of area
	No.	L.	B.	D.	
④ Patch repair over pot holes with 20mm Premix — E/H					
Qty. vide TMB P. (62)					
ino. (04) 28.59 m ²					
@ Rs 307.61/m ²					Rs 8795.00
⑤ Patch repair over bituminous surface with 20mm Premix — E/H					
Qty. vide TMB P. (63)					
ino. (05) 28.59 m ²					
@ Rs 327.45/m ²					Rs 9362.00
⑥ Maintenance of c/d works (H.P.)					
Qty. vide TMB P. (63)					
ino. (06) 1 nos					
@ Rs 1131.64/nos					Rs 1132.00
⑦ Maintenance of c/d works (slab)					
Qty. vide TMB P. (63)					
ino. (07) 1 nos					
@ Rs 2336.81/nos					Rs 2337.00
⑧ Maintenance of road sign					
Qty. vide TMB P. (63)					
ino. (08) 0.11 km					
@ Rs 1087.62/km					Rs 120.00
⑨ Maintenance of 200mm & km					
Qty. vide TMB P. (63)					
ino. (09) 0.13 km					
@ Rs 654.33/km					Rs 85.00

Continuation

C/o Rs 61340.00

