

Name of Road: - NH 101 TO RAGPUT TOLA

Schedule XLV-Form No. 134

Name of Agency: - Chauran Thuar (S.C.)

DIVISION

Block: - Daikunthpur

SUB-DIVISION

M.B.HD-572

MEASUREMENT BOOK

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
(1) Restoration of 2cm cuts/ Beams with soil-					
Qty vide TMBP-(35) item no (1)					
i.e. 11.88 m^3 @ $379.59/\text{m}^3$ ₹ = 4510.00					
(2) making up of Beams / shoulder-					
Qty vide TMBP-(35) item no (2)					
i.e. 185.49 m^2 @ $57.01/\text{m}^2$ ₹ = 10575.00					
(3) patch repair over bituminous surface-					
Qty vide TMBP-(36) item no (3)					
i.e. 10.11 m^2 @ $296.41/\text{m}^2$ ₹ = 2977.00					
(4) maintenance of Road Signs-					
Qty vide TMBP-(36) item no (4)					
i.e. 0.31 km @ $1054.28/\text{km}$ ₹ = 327.00					
(5) maintenance of 200m x km stone-					
Qty vide TMBP-(36) item no (5)					
i.e. 0.620 km @ $688.17/\text{km}$ ₹ = 427.00					
(6) Trimming of grass and weeds-					
Qty vide TMBP-(36) item no (6)					
i.e. 217.50 m^2 @ $2.17/\text{m}^2$ ₹ = 472.00					
(7) maintenance of tree by the road side-					
Qty vide TMBP-(36) item no (7)					
i.e. 22 nos @ $655.20/\text{Nos}$ ₹ = 14414.00					
= 33702.00					
Continuation					

Continuation