

1st year maintenance.			
Name of Road: - Pm pssy path.			
Haribela to Bela muslim tola.			
Ager - Jiten & Kumar.			
Agreement No - 385/01/21-22			
D.O.B	-	13/04/21	
D.O.C	-	12/04/22	
A.O.C	-	15/6/22.	
Item (1) Restoration of			
Raincuts with soil. - -			
Vide T.M.B Page (22)			
Qty = 37.11 M ³			
@ Rs = 404.06/M ³ - Rs. 23076-			
/			
Rs = 23076 = 0			

1

Particulars	Details of actual measurements				Contents of area
	No.	L.	B.	D.	
				BFMS =	23076 =
Item (2) Maintenance of					
making up of Besms					
Shoulders - - -					
Vide T.M.B Page - (22)					
Qty =		164.93/m ²			
Rs =		60.28/m ²		Nr	9942 =
Item (3) Maintenance of					
Bitumen mix seal surface					
Vide T.M.B Page - (23)					
Qty =		22.07 m ²			
Rs =		274.78/m ²			6064 =

Item (4) Maintenance					
of C/D Work (H.P.C)					
Vide T.M.B Page - (23)					
Qty =		2.00 Nos.			
Rs =		1166.58/Nos		Nr	2333 =
Item (5) Maintenance of					
Road Sign. - - -					
Vide T.M.B Page - (23)					
Qty =		0.12 Km.			
Rs =		1104.14/Km			132 =
Item (6) Maintenance of					
200m Stone & 1 Km Stone					
Vide T.M.B Page - (23)					
Qty =		0.14 Km.			
Rs =		641.92/Km			90 =

Continuation

Rs = 41637 =

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					BFMS = 41637 = 0
Item (7) cutting of branches of trees and shrub.					
vide T.M.B Page - 63					13500
Qty = 2.00/Nos					
@rs = 113.64/Nos - rs					227 = 0
Item (8) cutting of shrub.					
Roadway					
vide T.M.B Page - 63					
Qty = 10.00/Nos					
@rs = 698/Nos - rs					70 = 0
Item (9) trimming grass and weeds					

vide T.M.B Page - 63					
Qty = 23.63 ml					
@rs = 2.38/ml - rs					55.00
Item (10) white washing of					
c/d work proper wall					
vide T.M.B Page - 64					
Qty = 42.00 ml					31500
@rs = 16.83/ml - rs					709 = 0
13.500 ml - rs					42698 = 0
Add - 1% L.C - rs					427 = 0
12% 0.97 - rs					5124 = 0
10% S.F - rs					266.00
					rs = 48515 = 0

PPalal
19/6/24
JC

Continuation

AP
30/7/24