

N/Work:- Construction of MMGSY road from Kauri to Kauri  
Rein tola. Length of road - 1.500km -

## Schedule XLV-Form No. 134

MMGSY (GEM)

अधीन कार्य विभाग कार्य प्रगति सूची

DIVISION

अधीन कार्य विभाग कार्य प्रगति सूची SUB-DIVISION

WEASUREMENT BOOK

102295

Agency:- Uttar Bihar Construction Co. Motihari.

# 1st Year Maintenance Bill

38

Sch. XLV—Form No. 134

| Particulars                         | Details of actual measurement |    |    |    | Contents of area |
|-------------------------------------|-------------------------------|----|----|----|------------------|
|                                     | No.                           | L. | B. | D. |                  |
| Name of work: → Maintenance of Road |                               |    |    |    |                  |
| from Koyasi to Koyasi Rain Tola.    |                               |    |    |    |                  |
| Agency → M. S. Uttar Bihar Const.   |                               |    |    |    |                  |
| Company, Nalanda.                   |                               |    |    |    |                  |
| Agreement No. → 06/SPD/2017-20.     |                               |    |    |    |                  |
| dt of start - 30.09.2019.           |                               |    |    |    |                  |
| dt of completion - 29.06.2020.      |                               |    |    |    |                  |
| Actual completion → 15.04.2023      |                               |    |    |    |                  |
|                                     |                               |    |    |    |                  |
|                                     |                               |    |    |    |                  |
|                                     |                               |    |    |    |                  |
|                                     |                               |    |    |    |                  |
|                                     |                               |    |    |    |                  |
|                                     |                               |    |    |    |                  |
|                                     |                               |    |    |    |                  |
|                                     |                               |    |    |    |                  |
|                                     |                               |    |    |    |                  |

① Restoration of Rain cuts / Aerms with Soil masonry.

|                                               |
|-----------------------------------------------|
| 1x 6.75 x 0.75 x 0.300 = 1.52 m <sup>3</sup>  |
| 1x 7.50 x 1.00 x 0.300 = 2.25 m <sup>3</sup>  |
| 2x 5.50 x 0.85 x 0.300 = 2.81 m <sup>3</sup>  |
| 3x 6.00 x 1.00 x 0.300 = 5.40 m <sup>3</sup>  |
| 2x 9.85 x 0.85 x 0.300 = 5.03 m <sup>3</sup>  |
| 2x 7.75 x 1.00 x 0.300 = 4.65 m <sup>3</sup>  |
| 1x 4.00 x 0.75 x 0.300 = 0.90 m <sup>3</sup>  |
| 4x 7.00 x 1.00 x 0.300 = 8.40 m <sup>3</sup>  |
| 3x 9.00 x 0.85 x 0.300 = 6.88 m <sup>3</sup>  |
| 2x 11.00 x 1.00 x 0.300 = 6.60 m <sup>3</sup> |
| 2x 8.25 x 0.75 x 0.300 = 3.72 m <sup>3</sup>  |
| 4x 7.85 x 1.00 x 0.300 = 9.42 m <sup>3</sup>  |

Continuation

Qty = 57.58 m<sup>3</sup>

| Abstract of work                                                   |                       |    |           |
|--------------------------------------------------------------------|-----------------------|----|-----------|
| ① Restoration of rain water drains with soil mounds.               |                       |    |           |
| Qty vide Page no. 35 in RMB                                        |                       |    |           |
| @ 380.55/m <sup>3</sup>                                            | 73.91 m <sup>3</sup>  | Rs | 28129 = W |
| ② Maling up Berms / Shoulders                                      |                       |    |           |
| Stripps excess soil                                                |                       |    |           |
| Qty vide Page no. 39 in RMB                                        |                       |    |           |
| @ 58.37/m <sup>3</sup>                                             | 160.70 m <sup>3</sup> | Rs | 9380 = W  |
| ③ Repair of pot holes M.S.S. using bitumen binder 13.2 mm to 60 mm |                       |    |           |
| Qty vide Page no. 37 in RMB                                        |                       |    |           |
| @ 303.85/m <sup>2</sup>                                            | 10.31 m <sup>2</sup>  | Rs | 3133 = W  |
| ④ Maling up Road Sides                                             |                       |    |           |
| Qty vide Page no. 40 in RMB                                        |                       |    |           |
| @ 1074.51/m <sup>3</sup>                                           | 0.130 m <sup>3</sup>  | Rs | 140 = W   |
| Continuation                                                       |                       |    | 40782 = W |

Continuation

Sch XLV—Form No 134

| Particulars                       | Description of the local measurement |       |     |     | Contents of area |
|-----------------------------------|--------------------------------------|-------|-----|-----|------------------|
|                                   | No                                   | I     | II  | III |                  |
|                                   |                                      |       | 811 | 82  | 40782-00         |
| ① Maintenance of 2.0 m x 100 ft   |                                      |       |     |     |                  |
| At present Page no. (A) 10000     |                                      |       |     |     |                  |
| @ 100/100                         |                                      | 10000 |     | 83  | 10720            |
| ② cutting of branches of trees    |                                      |       |     |     |                  |
| At present Page no. (B) 10000     |                                      |       |     |     |                  |
| @ 100/100                         |                                      | 10000 |     | 83  | 21320            |
| ③ cutting of shrubs from road way |                                      |       |     |     |                  |
| At present Page no. (C) 10000     |                                      |       |     |     |                  |
| @ 60/100                          |                                      | 10000 |     | 83  | 2620             |
| ④ Trimming of grass & weeds       |                                      |       |     |     |                  |
| At present Page no. (D) 10000     |                                      |       |     |     |                  |
| @ 200/100                         |                                      | 10000 |     | 83  | 2620             |

|  |  |  |  |    |           |
|--|--|--|--|----|-----------|
|  |  |  |  | 83 | 41,164-00 |
|  |  |  |  | 83 | 4200      |
|  |  |  |  | 83 | 41,160-00 |

AB

19/5/2017

Balal Singh

19.5.2017

Material Statement

210 - 73.91 m<sup>3</sup>231 - 0.004 m<sup>3</sup>590 - 0.020 m<sup>3</sup>Stone masonry - 0.28 m<sup>3</sup>

AB

19/5/2017