

ਸਰਕਾਰੀ ਆਰਕਾਈਵ ਵਿਭਾਗ ਲਿਖਤ ਦਫ਼ਤਰ

MMGSY(5E)

Schedule XLV-Form No. 134

ਦਫ਼ਤਰ

DIVISION

52167

SUB-DIVISION

Measurement Book

1519

ਸਿਰ:- ਵਿਭਾਗ 52167

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year Mainstan B-11					6
Name of work - chouse-Dhau 2					
Road to chilhar harizan Tol					
Agency - Nitish Kumar					
Ag No - 26 SPD/19-20					
① Restoration of raincults					
5 x 15m x 1.125 x 0.30 = 25.312m ³					
10m x 1.125 x 0.25 = 2.812m ³					
					28.124m ³
② making up shoulders					2
6 x 30m x 1.125 = 202.50m					
③ Repair of Pot holes by WBM B-3					
3 x 3.10m x 1.35 x 0.075 = 0.941m ³					
4 x 3.90m x 1.20 x 0.075 = 1.17m ³					
					2.111m ³
Repair to					
④ Pot hole and removing loose material.					
$\frac{2.111}{0.075} = 28.146m^2$					
Net = 28.13m ²					
⑤ Pot hole repair by mix seal surfacing					
Nete item ④ = 28.13m ²					
⑥ Maintenance of C-1 No.					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑦ Maintenance of Road Sign-008					
⑧ Maintenance of 200m fence post-0.09 Km					
⑨ cutting of branches of tree & shrubs, No					
⑩ White wash up to coats					
$2 \times 6.15m \times 0.40 = 4.92m^2$					
$2 \times 2 \times 6.15m \times 0.60 = 14.76m^2$					
$4 \times 0.60m \times 0.40 = 0.96m^2$					
					$20.64m^2$
1200m					
Abstract of City and cant					
① Restoration of rainwater					
$\text{Vide P-39} = 28.124m^3$					
@ Rs 352.83/m ³					Rs 9923.70
② Maintenance of shoulders					
$\text{Vide P-39} = 202.50m^2$					
@ Rs 58.57/m ²					Rs 11860.70
③ Repair to pot holes by 100mm G.O.					
$\text{Vide P-39} = 2.11m^3$					
@ Rs 523.99/m ³					Rs 1106.70
④ Repair to pot holes by 100mm loose material vide P-39					
$= 28.13m^2$					
@ Rs 310.61/m ²					Rs 8725.70
⑤ Repair to pot holes by					

Continuation

Rs 31668.70

Continuation